# **User Manual**

**Vision Sensors** 

## **VG Series**

Thank you for purchasing an Autonics product. This user manual contains information about the product and its proper use, and should be kept in a place where it will be easy to access.

www.autonics.com

## Autonics

## Preface

Thank you for purchasing an Autonics product.

This user manual contains information about the product and its proper use, and should be kept in a place where it will be easy to access.

## **User Manual Guide**

- Please familiarize yourself with the information in this manual before using the product.
- This manual provides detailed information on the product's features. It does not offer any guarantee concerning matters beyond the scope of this manual.
- This manual may not be edited or reproduced in either part or whole without permission.
- This programming manual is not provided as part of the product package. Please visit our home-page (www.autonics.com) to download a copy.
- The manual's content may vary depending on changes to the product's software and other unforeseen developments within Autonics, and is subject to change without prior notice. Upgrade notice is provided through our homepage.
- We contrived to describe this manual more easily and correctly. However, if there are any corrections or questions, please notify us these on our homepage.

## **User Manual Symbols**

Symbol	Description		
Note	Supplementary information for a particular feature.		
<b>Warning</b> Failure to follow instructions can result in serious injury or death.			
A Caution	Failure to follow instructions can lead to a minor injury or product damage.		
<b>Ex.</b> An example of the concerned feature's use.			
×1	Annotation mark.		

## **Safety Considerations**

- Following these safety considerations will ensure the safe and proper use of the product and help prevent accidents, as well as minimizing possible hazards.
- Safety considerations are categorized as Warnings and Cautions, as defined below:

Marning	Warning	Failure to follow the instructions may lead to a serious injury or accident.

CautionFailure to follow the instructions may lead to a minor injury or accident.
--



 Fail-safe device must be installed when using the unit with machinery that may cause serious injury or substantial economic loss. (e.g. nuclear power control, medical equipment, ships, vehicles, railways, aircraft, combustion apparatus, safety equipment, crime/disaster prevention devices, etc.)

Failure to follow this instruction may result in personal injury, fire, or economic loss.

- Do not use this product for protecting human body or part of body.
- Do not see light LED directly or direct beam at person.
   Failure to follow this instruction may result in damage on eyes.
- Do not connect, repair, or inspect the unit while connected to a power source.
   Failure to follow this instruction may result in fire.
- Check connections and connect cables.
   Failure to follow this instruction may result in fire.
- Do not disassemble or modify the unit.
   Failure to follow this instruction may result in fire.

## <u> (</u>Caution

- Use the unit within the rated specifications.
   Failure to follow this instruction may result in fire or product damage.
- Use dry cloth to clean the unit. Do not use water or organic solvent when cleaning the unit.
   Failure to follow this instruction may result in fire.
- Do not use the unit where flammable/explosive/corrosive gas, humidity, direct sunlight, radiant heat, vibration, impact or salt may be present.
   Failure to follow this instruction may result in fire or explosion.
- Keep metal chip, dust and wire residue from flowing into the unit.
   Failure to follow this instruction may result in fire or product damage.

## The above specifications are subject to change and some models may be discontinued without notice.

Be sure to follow cautions written in the instruction manual, user manual and the technical descriptions (catalog, homepage).

## **Caution during Use**

- Follow instructions in Cautions during Use. Otherwise, it may cause unexpected accidents.
- 24VDC power supply should be insulated and limited voltage/current or Class 2, SELV power supply device.
- In order to avoid malfunction from static electricity or noise, ground shield wire of the power I/O cable.
- Do not disconnect the power supply while setting operation or saving set information. It may cause data loss.
- Do not disconnect the power supply while updating firmware. It may cause product damage.
- Keep optical section of the sensor away from the contact with water, dust and oil. It may cause malfunction.
- When changing the light or filter, use the assembly tool and observe installation instruction.
- When the sensor is not used for a long time, separate the power cable to store.
- When connecting network, connection must be operated by technical expert.
- In the following case, disconnect the power supply immediately. It may cause fire or product damage.
  - 1 When water or foreign substance is detected in the product
  - ② When the product is dropped or case is damaged
  - $\ensuremath{\mathfrak{I}}$  When smoke or smell is detected from the product
- Do not use the product in the place where strong magnetic field or electric noise is generated.
- This unit may be used in the following environments.
  - 1 Indoor (in the environment conditions in specifications)
  - 2 Altitude max. 2,000m
  - ③ Pollution degree 2
  - (4) Installation category II

## **Table of Contents**

	Prefac	се	iii
	User I	Manual Guide	iv
	User I	Manual Symbols	V
	Safety	y Considerations	vi
	Cautio	on during Use	vii
	Table	of Contents	ix
1	Prod	luct Instruction	11
	1.1	Features	11
	1.2	Accessory and sold separately	
		<b>1.2.1</b> Overall configuration diagram	
		1.2.2 Accessory	
		1.2.3 Sold separately	14
	1.3	Ordering Information	16
	1.4	Unit Description	17
2	Spec	cifications	19
3	Dime	ensions	21
-	3.1	Body	
	3.2	Bracket	
		<b>3.2.1</b> Bracket A (BK-VG-A)	
		<b>3.2.2</b> Bracket B (BK-VG-B)	
	3.3	Cable	22
		3.3.1 Power I/O cable	22
		3.3.2 Ethernet cable	22
4	Conr	nections	23
	4.1	Power I/O Cable (M12 12-pin connector)	24
		4.1.1 Input	25
		<b>4.1.2</b> Output (OUT0 to OUT3)	25
	4.2	Ethernet Cable (M12 8-pin/RJ45 connector)	26
5	Insta	Illation	27
	5.1	Working Distance and FOV by Effective Focal Length	
	5.2	Installation of Vision Sensor	
	5.3	Focus Adjustment	29
	5.4	Replacement of Light and Filter	
		<b>5.4.1</b> Replacement of color filter or polarizing filter	30
		5.4.2 Replacement of light	
6	Visio	on Sensor Program [Vision Master]	33
	6.1	Overview	33
	6.2	Vision Master Work Flow	
		6.2.1 Setting mode	37

		6.2.2	Operation mode	
	6.3	Installa	tion of Vision Master	
		6.3.1	System requirements	
		6.3.2	Installation of the program	
		6.3.3	Installation folder structure	
		6.3.4	Removal of the program	
		6.3.5	Network setting	
	6.4	Start ar	nd Exit	47
		6.4.1	Start	
		6.4.2	Exit	
	6.5	Vision I	Master Screen Layout	48
		6.5.1	Menu	
		6.5.2	Toolbar	
	6.6	Setting	Menu	57
		6.6.1	Network	
		6.6.2	Camera	
		6.6.3	Input	
		6.6.4	Output	71
		6.6.5	Work Group	75
		6.6.6	Inspection	79
	6.7	Inspect	tion	82
		6.7.1	Alignment	
		6.7.2	Brightness	
		6.7.3	Contrast	
		6.7.4	Area	91
		6.7.5	Edge	
		6.7.6	Shape comparison	
		6.7.7	Length	
		6.7.8	Angle	
			Diameter	
			Object counting	
			Color identification	
			Object of color counting	
7	Sottin			
'	7.1	•		
	7.2	Device	(Vision Sensor)	121
8	Troub	leshoo	oting	125

## **1 Product Instruction**

#### 1.1 Features

VG series, vision sensor, is the light and sensor integrated type which has 13 types of inspection functions, so that it can be applied and utilized for various environment and condition. Before applying to actual environment to utilize, using simulator can realize inspection.

Since it is available to set 32 work groups and 64 inspection items for each work group, vision sensor can flexibly response to the change of work environment.


Furthermore, parameter setting and monitoring from PC is simple through Ethernet communication.

- Light integrated vision sensor
- Minimized image distortion with global shutter method
- Proprietary technology to block optical interference to improve optical performance (patent)
- Stronger in environment of vibration or impact with lens cover detachment prevention technology
- Various inspection function: alignment, brightness, contrast, area, edge, shape comparison length, angle, diameter, object counting, color identification, area of color, object of color counting
- Flexible response to changing work environment by setting 32 work groups (64 inspection items for each work group)
- Easy work group managing and parameter setting
   Through vision sensor program (Vision Master), it is available to copy or save work group saved in vision sensor to PC or work group saved in PC to vision sensor.
- Real-time monitoring of inspection result


   Through vision sensor program (Vision Master), it is available to monitor the Pass/Fail inspection result of inspection items in real-time. Furthermore, statistics data of the inspection result can be generated, and it can be also initialized during inspection.
- Realization of inspection by simulator
   Through vision sensor program (Vision Master), it is available to register work group with an image saved in PC to test inspection, without vision sensor.
- Saving data to FTP server
   : According to the settings, an inspection result image can be transmitted and saved in FTP server. Furthermore, setting the file naming rule can help to manage file.
- Applicable to various environment with various light and filter
  - 4 types of light (white/red/green/blue)
  - 4 types of color filter (red/green/blue/infrared blocking)
  - Polarizing filter (window/red/green/blue/infrared blocking)
- Protection structure IP67 (IEC standard)

### 1.2 Accessory and sold separately

#### 1.2.1 **Overall configuration diagram**



#### 1.2.2 Accessory





 Visit our homepage (www.autonics.com) to download vision sensor program (Vision Master).
 Before using the product, please check whether all accessories above are included. If there is a damaged or missing accessory, please contact Autonics sales team or retailer.



Please refer to the model name below, when purchasing the lost accessory.

Assembly tool





#### 1.2.3 Sold separately

Light<sup>\*</sup>

LR-W-06-VG (white)	LR-R-06-VG (red)	LR-G-06-VG (green)	LR-B-06-VG (blue)				

\*Besides offered light, another type of lights are sold separately.

Color filter

FL-R-VG	FL-G-VG	FL-B-VG	FL-IC-VG
(red)	(green)	(blue)	(infrared blocking)

Polarizing filter

.

i olanzing mo				
FL-P-VG (window)	FL-RP-VG (red)	FL-GP-VG (green)	FL-BP-VG (blue)	FL-ICP-VG (infrared blocking)
0				
Power I/O cable				
CID-2-VG (length: 2m)			-VG (length: 2m)	

CID-2-VG (length: 2m) CID-5-VG (length: 5m) CID-10-VG (length:10m)	CLD-2-VG (length: 2m) CLD-5-VG (length: 5m) CLD-10-VG (length:10m)



Ethernet cable	
CIR-2-VG (length: 2m)	CLR-2-VG (length: 2m)
CIR-5-VG (length: 5m)	CLR-5-VG (length: 5m)
CIR-10-VG (length:10m)	CLR-10-VG (length:10m)
Protection cover <sup>*</sup>	Bracket B
P96-M12-1	BK-VG-B


Protection cover protects unused connectors from foreign substances.

When installing the protection cover, please tighten the cover with hand.

Vision panel




## 1.3 Ordering Information



Items	Description		
① Item	V	Vision sensor	
② Type	G	General inspection	
Image element	М	Mono CMOS	
③ Image element	С	Color CMOS	
④ Resolution (pixel)	04	752×480	
	W	White	
A light	R	Red	
5 Light	G	Green	
	В	Blue	
	8	8mm	
6 Effective focal length	16	16mm	
	25	25mm	
⑦ Communication E		Ethernet (TCP/IP)	

×1. Light can be purchased separately.

### 1.4 Unit Description



- Lens cover: Front cover of lens
   ※In case using a filter (color filter/polarizing filter), separate the lens cover with the assembly tool before insert the filter.
- 2 Lens: There are 8mm, 16mm, 25mm models by effective focal length.
- ③ Light cover: Light cover fixes inner LED lights.
- Light: Inner LED lights
   XIn order to change the light, separate lens cover and light cover.
- (5) Bracket mounting hole on back side: Install the vision master from the back side using bracket B.
- 6 Power I/O connector: Connect the power I/O cable.
- ⑦ Ethernet connector: Connect the Ethernet cable. It is for TCP/IP communication.
- ⑧ Focus adjuster: After fixing vision sensor, adjust focus by rotating the focus adjuster.
- Indicators

Indicator		Color	Descriptions
POWER	Power indicator	Green LED	Turns ON when power is supplied.
LINK	NK Ethernet connection Gr		Turns ON when vision sensor is connected with PC (Ethernet communication).
DATA	Data transmission indicator	Orange LED	Flashes when data is transmitted from vision sensor to PC.
FAIL	Failure indicator	Red LED	Flashes when detects failure during work group inspection.
PASS Pass indicator Gree		Green LED	Flashes when passed inspection during work group inspection.

## 2 Specifications

Model	Model		VG- M04⊡-	VG- M04⊡-	VG- C04⊡-	VG- C04⊡-	VG-C C04⊡-			
		M04⊡- 8E	16E	25E	8E	16E	25E			
Effective f	ocal length	8mm	16mm	25mm	8mm	16mm	25mm			
Min. work	ing distance	50mm	100mm	200mm	50mm	100mm	200mm			
Power sup	oply	24VDC	(±10%)							
Current co	onsumption	1A			•					
Inspectior	Inspection item	area, edge	, brightness e, shape co gle, diamete	mparison,	Alignment, brightness <sup>*2</sup> , contrast <sup>*2</sup> , area <sup>*2</sup> , edge, shape comparison <sup>*2</sup> , length, angle, diameter, object counting <sup>*2</sup> , color identification, area of color, object of color counting					
	Work group	32	32							
	Simultaneous inspection	64								
Camera frame per second <sup>≍1</sup>		Max. 60fps								
	Image filter	Preprocessing, external filter (color filter, polarizing filter)								
	Image element	1/3 inch mono CMOS     1/3 inch color CMOS								
Imaga	Resolution	752×480 pixel								
lmage snap	Camera frame per second <sup>×1</sup>	Max. 60fps								
	Shutter	Global shutter								
	Exposure time	20 to 10,000us								
Light	ON/OFF method	Pulse								
-	Color	White, red, green, blue								
Trigger mo	ode	External trigger, internal trigger, free-run trigger								
	Signal	Rated input 24VDC= (±10%)								
Input	Туре	External trigger (TRIG), work group change (IN0 to IN3), alarm cleared (IN0 to IN3), encoder (IN2, IN3)								
	Signal	NPN or PNP open collector output								
-	olghai	Max. 24VDC 50mA, residual voltage: max. 1.2VDC								
Output	Туре	: inspectio	Control output (OUT0 to OUT3) : inspection completion, inspection result, external light trigger, alarm, camera busy, changing work group completed							
FTP transmission		Possible								
Communi	cation	Ethernet(TCP/IP), 100BASE-TX/10BASE-T								
Protection	i circuit	Output short over current protection circuit								

Model		VG- M04⊡- 8E	VG- M04⊡- 16E	VG- M04⊡- 25E	VG- C04⊡- 8E	VG- C04⊡- 16E	VG-C C04⊡- 25E		
Indicator		(LINK), p · Data tra	<ul> <li>Power indicator (POWER), Ethernet connection indicator (LINK), pass indicator (PASS): green LED</li> <li>Data transmission indicator (DATA): orange LED</li> <li>Failure indicator (FAIL): red LED</li> </ul>						
Insulation	n resistance	Over 20M	Ω (at 500VI	DC megger)					
Dielectric	c strength	500VAC 5	0/60Hz for	1 min					
Vibration		1.5mm amplitude at frequency of 10 to 55Hz (for 1 min) in each X, Y, Z direction for 2 hours							
Shock		300m/s <sup>2</sup> (approx. 30G) in each X, Y, Z direction for 3 times							
Environ	Ambient temp.	0 to 45℃, storage: -20 to 70℃							
ment <sup>**3</sup>	Ambient humi.	35 to 85%	RH, storage	e: 35 to 85%	6RH				
Protectio	n structure	IP67 (IEC standard)							
Material		Case: aluminum, lens cover/focus adjuster: polycarbonate, cable: polyurethane							
Accesso	ries	Assembly tool, bracket A, mounting screw: 2							
Sold sep	arately	Light, color filter, polarizing filter, power I/O cable, Ethernet cable, bracket B, protection cover, vision panel							
Approval		CE, 🖾 🗆							
Weight <sup>≋4</sup>		Approx. 415g (approx. 273g)	Approx. 416g (approx. 274g)	Approx. 416g (approx. 274g)	Approx. 415g (approx. 273g)	Approx. 416g (approx. 274g)	Approx. 416g (approx. 274g)		

 $\times$ 1. The number of camera frames per second can be different by image setting or inspection item.

 $\times$ 2. These inspections identify data by converting the color image to the mono image.


 $\times$ 3. Environment resistance is rated at no freezing or condensation.

 $\times$ 4. The weight includes packaging. The weight in parenthesis is for unit only.

## 3 Dimensions


3.1 **Body** 

(unit: mm)




### 3.2 Bracket

#### 3.2.1 Bracket A (BK-VG-A)



3.2.2 Bracket B (BK-VG-B)




### 3.3 Cable

(unit: mm)

#### 3.3.1 **Power I/O cable**

#### (1) CID Series




#### (2) CLD Series




%L(m): 2m, 5m, 10m
Please refer to the cable length.

#### 3.3.2 Ethernet cable

#### (1) CIR Series




#### (2) CLR Series



X L(m): 2m, 5m, 10mPlease refer to the cable length.

## 4 Connections




Were the product which of power supply is 24VDC.When selecting a product, please refer to Autonics selection guide.

## 4.1 **Power I/O Cable (M12 12-pin connector)**


Pin arrangement	Pin No.	Cable color	Signal	Function					
	1	Brown	24VDC	24VDC					
	2	Blue	GND	GND					
	3	White	TRIG	Trigger input					
	4	Green	IN0	Work group change Bit 0	Work group change - Clock				
	5	Pink	IN1	Work group change Bit 1	Work group change - Data				
9 10 3 8 12 11 4	6	Yellow	IN2	Work group change Bit 2					
765	8	Gray	IN3	Work group change Bit 3	Encoder - Down counter - Quadrature B				
	11	Gray/Pink	COMMON	COMMON					
	7	Black	OUT0						
	9	Red	OUT1	Inspection completion, inspection result,					
	10	Purple	OUT2	external light trigger, alarm, camera busy, changing work group completed					
	12	Red/Blue	OUT3						

#### 4.1.1 Input

#### (1) External trigger input (TRIG), Work group change input (IN0 to IN3) Alarm cleared (IN0 to IN3)




#### (2) Encoder input (IN2, IN3)




#### 4.1.2 Output (OUT0 to OUT3)

#### (1) NPN open collector output




#### (2) PNP open collector output



## 4.2 Ethernet Cable (M12 8-pin/RJ45 connector)


Din errengement	M12 8-pin	1	Cable color	RJ45		
Pin arrangement	Pin No.	Signal		Pin No.	Signal	
	6	RX+	White/Orange	1	TX+	
	4	RX-	Orange	2	TX-	
	5	TX+	White/Green	3	RX+	
	8	TX-	Green	6	RX-	
4	1	-	White/Blue	5	-	
5 • 6	7	-	Blue	4	-	
	2	-	White/Brown	7	-	
	3	-	Brown	8	-	

## 5 Installation




### 5.1 Working Distance and FOV by Effective Focal Length

Please check working distance by effective focal length and FOV (Field of View).



Effective focal length(f)	8mm	16mm	25mm
Min. working distance	50mm	100mm	200mm
Brightness	F2.0	F2.5	F2.5




\*Sensing range by effective focal length (unit: mm)


Effective focal length	Working distance	50	100	200	300	400	500	600	700	800	900	1,000
	FOV	16	32	64	96	129	161	193	255	257	289	322
8mm	Horizontal axis (H)	27	54	108	163	217	271	325	380	434	488	542
	Vertical axis (V)	17	35	69	104	138	173	208	242	277	311	346
	FOV	_	16	33	49	66	82	99	155	132	148	165
16mm	Horizontal axis (H)	—	28	56	83	111	139	167	195	222	250	278
	Vertical axis (V)	_	18	35	53	71	89	106	124	142	160	177
	FOV	_	_	23	34	46	57	68	80	91	103	114
25mm	Horizontal axis (H)	—	—	38	58	77	96	115	134	154	173	192
	Vertical axis (V)	_	_	25	37	49	61	74	86	98	110	123

### 5.2 Installation of Vision Sensor

1st Fix vision sensor using bracket.




2nd Place the sensing target at the center of the vision sensor lens.



## 5.3 Focus Adjustment

After installing and running Vision Master, use the focusing guide function to adjust the focus. Using (-) screwdriver, turn focus adjuster to right and left to adjust the focus.




\*Please refer to '6.3 Installation of Vision Master' for the installation of Vision Master and network setting.

XPlease refer to '6.6.2 Camera (6) Focusing guide ' for the focusing guide.


### 5.4 **Replacement of Light and Filter**

#### 5.4.1 **Replacement of color filter or polarizing filter**

1st Put and fix the assembly tool into the groove on the side of the vision sensor.



2nd While fixing the vision sensor with the assembly tool, hold the lens cover and disassemble it in a counter clock wise direction.




3rd Instead of the disassembled lens cover, assemble another color filter or polarizing filter in clock wise direction.


#### 5.4.2 Replacement of light


1st Put and fix the assembly tool into the groove on the side of the vision sensor.

- 2nd While fixing the vision sensor with the assembly tool, hold the lens cover and disassemble it in a counter clock wise direction.
- 3rd Disassemble the light cover using the (+) screwdriver, and disassemble the inner LED light.




4th Place the connection pin of PCB of the inner LED light to face the direction of 6 o'clock and assemble it to the vision sensor body.





5th Align the light cover with the groove in the direction of 12o'clock and fix it with the screw. Tighten them with the 1.2kgf·cm of tightening torque.



6th Assemble the disassembled lens cover in clock wise direction.


## 6 Vision Sensor Program [Vision Master]

#### 6.1 **Overview**

Vision Master is the vision sensor program that is connected with VG Series, Autonics vision sensor, to utilize it.

Vision Master provides graphic user interface to make setting parameter and managing monitoring data of vision sensor easy.

It is connected with vision sensor through Ethernet (TCP/IP) and exchange data with vision sensor.



ltem	Description							
item .		distered image and input image	e to search for a similar					
	Compares features of the registered image and input image to search for a similar pattern position, and inspects the input image with information of the searched pattern position and rotation angle.							
	<template></template>	<pass></pass>	<fail></fail>					
Alignment								
	Inspects brightness of the R the ROI (Region of Interest)	OI in the input image based on in the registered image.	the mean brightness value of					
Brightness	<template></template>	<pass></pass>	<fail></fail>					
	Inspects contrast of the ROI in the input image based on contrast of the ROI in the registered image.							
	<template></template>	<pass></pass>	<fail></fail>					
Contrast	Autonics	zsinotuA	Autonics					
	Inspects the ROI area of the by user.	input image based on the ROI	area of the image registered					
	<template></template>	<pass></pass>	<fail></fail>					
Area		E.						
	Inspects the direction of the edge in the input image based on the edge registered by user in the same area.							
<b>−</b> Edge	<template></template>	<pass></pass>	<fail></fail>					

### **Autonics**


Item	Description							
	Compares shape of object in the ROI registered by user and that of the input image.							
Shape comparison	<template></template>	<pass></pass>	<fail></fail>					
	Inspects the input image bas	ed on the length between two	edges registered by user.					
<b>→ िि</b> Length	<template></template>	<pass></pass>	<fail></fail>					
	Inspects the input image bas	ed on the angle between two e	edges registered by user.					
Angle	<template></template>	<pass></pass>	<fail></fail>					
	Inspects the input image bas	ed on the area between two ci	rcles registered by user.					
Diameter	<template></template>	<pass></pass>	<fail></fail>					

Item	Description							
	Compares the number of objects in the ROI which is in the image registered by user and that in the input image. Template>							
Object counting			the second secon					
	Compares color of the ROI r	egistered by user and that of th	he input image.					
Color identification	<template></template>	<pass></pass>	<fail></fail>					
	Compares the area of a certain color in the ROI registered by user and that in the input image.							
Area of color	<template></template>	<pass></pass>	<fail></fail>					
	Compares the number of objects in a certain color which are in the ROI of registere image and that of the input image.							
+ + Object of color counting	<template></template>	<pass></pass>						


%Color identification, area of color, and object of color counting are only for VG-C Series.

# 6.2 Vision Master Work Flow

# 6.2.1 Setting mode



# 6.2.2 **Operation mode**



# 6.3 Installation of Vision Master

# 6.3.1 System requirements

ltem	Minimum specifications	
System	32bit (×86) or 64bit (×64) processor over 1GHz	
Operations	Microsoft Windows 7/8/10	
Memory	1GB+	
Hard disk	400MB+ of available hard disk space	
VGA	Resolution: 1024×768 or higher	
Others	RJ45 Ethernet port	

# 6.3.2 Installation of the program

1st Download Vision Master program at Autonics web page(<u>www.autonics.com</u>).

- 2nd Close all programs before you start Vision Master installation. Double-click Vision Master setup.exe to start installation.
- 3rd When Installer Language window appears, select the language and click [OK] button.

	Installer Language	
	Please select the	e language of the installer
	English	<b></b>
		DK Cancel
4th (	Click [Next] button in the	e installation welcome window.
	🕓 Vision Master 1.0.6.27 Setu	ip 🗖 🔁 🗮 🗙
	Autonics Sensors & Controllers	Welcome to Vision Master 1.0.6.27 Setup Setup will guide you through the installation of Vision Master 1.0.6.27. It is recommended that you dose all other applications before starting Setup. This will make it possible to update relevant system files without having to reboot your computer. Click Next to continue.
		Next > Cancel

6th

5th This process is license agreement.

You can check whole part of license agreement article by rolling mouse scroll downward, clicking downward arrow or press "Page Down(PgDn)" Key of the keyboard. Please read the articles thoroughly before click [I Agree] button.

🕖 Vision Master 1.0.6.27 Setup			
License Agreement Please review the license terms before installing Vision Master 1.0.6.27.	5		
Press Page Down to see the rest of the agreement.			
AUTONICS END USER SOFTWARE LICENSE TERMS IMPORTANT - READ BEFORE COPYING, INSTALLING OR USING "Vision Master" (hereinafter referred to as, the "Software"). Do not use or load this software and any associated materials (collectively, the "Software") until you have carefully read the following terms and conditions. By loading or using the Software, you agree to the terms of this Agreement. If you do not wish to so agree, do not install or use the Software.			
License Terms and Conditions. This Software is licensed for use only in conjunction with Autonics Corporation (hereinafter referred to as ""Autonics"") component products. Use of the Software	ein 👻		
If you accept the terms of the agreement, click I Agree to continue. You must acce agreement to install Vision Master 1.0.6.27.	pt the		
Nullsoft Install System v3.01	Cancel		
Default installation path is as follows.			
C:\Program Files (x86)\Autonics\Vision Master\ Click [OK] button to install the program in the default installation pa	ath.		
C:\Program Files (x86)\Autonics\Vision Master\ Click [OK] button to install the program in the default installation pa Vision Master 1.0.6.27 Setup			
C:\Program Files (x86)\Autonics\Vision Master\ Click [OK] button to install the program in the default installation pa			
C:\Program Files (x86)\Autonics\Vision Master\ Click [OK] button to install the program in the default installation pa Vision Master 1.0.6.27 Setup Choose Install Location			
C:\Program Files (x86)\Autonics\Vision Master\ Click [OK] button to install the program in the default installation pa Vision Master 1.0.6.27 Setup  Choose Install Location Choose the folder in which to install Vision Master 1.0.6.27. Setup will install Vision Master 1.0.6.27 in the following folder. To install in a different	nt folder,		
C:\Program Files (x86)\Autonics\Vision Master\ Click [OK] button to install the program in the default installation pa Vision Master 1.0.6.27 Setup  Choose Install Location Choose the folder in which to install Vision Master 1.0.6.27.  Setup will install Vision Master 1.0.6.27 in the following folder. To install in a different dick Browse and select another folder. Click Install to start the installation.  Destination Folder	nt folder,		

7th Click [Install] button to install the program in the default installation path. If you want to install the program in another installation path, click [Browse..] button to designate a folder you want to install in and click [OK] button.

🥹 Browse For Folder	×
Select the folder to install Vision Master 1.0.6.27 in:	
📃 Desktop	
D Contraction Contractico C	
▷ 🚺 Autonics	
D 🖳 Computer	
Network	
🎍 vision master	
Make New Folder OK Cance	

8th Installation progress is displayed in the status window as follows.

Vision Master 1.0.6.27 Setup			
Installing Please wait while Vision Master 1.0.6.2	27 is being installed.		5
Created uninstaller: C:₩Program Files	(x86)₩Autonics₩Vision	Master₩uninsta	l.exe
Show details			
Nullsoft Install System v3,01			
	< Back	Next >	Cancel


9th Installation Complete window appears after installation is completed.

If the check box in the Installation Complete window is checked, Vision Master runs upon completion of installation.

You can run Vision Master by double-clicking the Vision Master icon on the desktop.

Vision Master 1.0.6.27 Setu	Vision Master 1.0.6.27 Setup		
Autonics Sensors & Controllers	Completing Vision Master 1.0.6.27 Setup Vision Master 1.0.6.27 has been installed on your computer.		
	Click Finish to close Setup.		
	Run Vision Master 1.0.6.27		
	< Back Finish Cancel		

The initial screen displays as follows.




# 6.3.3 Installation folder structure

This section explains the folder structure created when you installed Vision Master.

The Vision Master folder is created in [C:\Program Files (x86)\Autonics\] as a subfolder unless you select a new destination to change location of Vision Master folder.

After Vision Master is installed completely, Vision Master installation folder and related folders are created as follows in [C:\Users\(Account name)\Documents\Autonics\] as subfolders and work groups and documents are saved in. The program and all relevant documents are stored in these folders.



### (1) Image folder

If Save Result Image inspection parameter of Vision Master is set to ON, inspection result images are saved in the designated location. Saving location is fixed, so that is cannot be changed by user.

Inspection result images are saved in [C:\Users\(Account name)\Documents\Autonics\Vision Master\Image\ResultImage].

#### (2) Sample folder

This folder contains work groups for samples. Load sample files from this folder to Vision Master to test inspection.

#### (3) Work folder

When saving work groups from Vision Master to PC, the work groups are saved in this folder. When copying work groups from a device to PC using work group manager, the work groups are saved in this folder. If the saving location is changed when saving work groups in PC, work groups are saved in

If the saving location is changed when saving work groups in PC, work groups are saved in the changed folder.

## (4) Log folder

Log files of connection/disconnection with a device or inspection result are saved.

# 6.3.4 **Removal of the program**

There are procedures to uninstall Vision Master, Start > Program > Vision Master > Uninstall or Start > Setting > Control Panel > Add/Remove a Program > Vision Master.

When a confirmation window appears after selecting Remove, click [Yes] button to remove Vision Master from the computer.

# 6.3.5 Network setting

Change the network settings in Vision Master to connect with a device (vision sensor).

When executing Vision Master, Select Device window appears. Simulator or connected devices are displayed in the window. You can check connectable devices and connected devices using Refresh icon ( ) on the top of the window.

		T ICUSC	select simulator or device t		G
	Device		IP Address	MAC Address	Connectable staus
	🔒 Sin	nulators			
•	*	VG-M04			
	<u>.</u>	VG-C04			
	🔒 De	vices			
	91	VG-M04W-16E	192.168.0.2	58:E8:08:00:26:D1	٥
	- 11	VG-C04W-8E	210.124.103.194	58:E8:08:00:37:36	٥
	- 11	VG-C04W-8E	210.124.103.246	58:E8:08:00:19:C6	٥
	- 11	VG-C04W-8E	210.124.103.7	58:E8:08:00:25:ED	٥
	- 11	VG-C04W-25E	210.124.103.189	58:E8:08:00:3A:4B	a

Factory default of the device (vision sensor) is as follows.

IP address	192.168.0.2
Subnet mask	255.255.255.0
Gateway	192.168.0.1

# Note

A list of the currently connected vision sensor is displayed. After checking "connectable status" indicator, and connect a vision sensor.

- Connectable
- Our Contract Unconnectable

- The vision sensor is not connectable because it is connected to another PC already.

	Pleas	se select simulator or device	to connect.	G
Device		IP Address	MAC Address	Connectable stau
🔒 Si	mulators			
	VG-M04			
	VG-C04			
🔒 De	evices			
1	VG-M04W-16E	192.168.0.2	58:E8:08:00:26:D1	٥
1	VG-C04W-8E	210.124.103.194	58:E8:08:00:37:36	۰
- 11	VG-C04W-8E	210.124.103.246	58:E8:08:00:19:C6	٥
- 1	VG-C04W-8E	210.124.103.7	58:E8:08:00:25:ED	٥
1	VG-C04W-25E	210.124.103.189	58:E8:08:00:3A:4B	0

# (1) Change of device IP address

You can change IP address of the device to connect.

1st Select the device to connect, and click "After IP change, connect" button.

	Pleas	e select simulator or device t	o connect.	
	Device	IP Address	MAC Address	Connectable s
	🔐 Simulators			
	₩ VG-M04			
	品 VG-C04			
	🔐 Devices			
•	10 VG-M04W-16E	192.168.0.2	58:E8:08:00:26:D1	٩
	1 VG-C04W-8E	210.124.103.194	58:E8:08:00:37:36	٥
	VG-C04W-8E	210.124.103.246	58:E8:08:00:19:C6	•
	10 VG-C04W-8E	210.124.103.7	58:E8:08:00:25:ED	٥
	VG-C04W-25E	210.124.103.189	58:E8:08:00:3A:4B	0
	Manual IP Address Searching	🗸 Connect after changing i	IP 🗸 ОК	Canc

Change Network Setting 🛛 🔊				
IP Address	210, 124, 103, 3			
Subnet mask	255, 255, 255, 0			
Gateway	210, 124, 103, 1			
V	OK 🗙 Cancel			



If changed IP address is same with another IP address which is used in another PC of device, network error can occurs due to IP address conflicts.

#### (2) Manual search of IP address

If a device is not recognized while it is connected, click "Manual IP Address Searching" and search IP address of the device to connect.

(This is usable only when Gateway of the device and PC are same.)

Manual IP Address Searching			
210, 124, 103, 7			
✓ ОК	X Cancel		


# 6.4 Start and Exit

# 6.4.1 Start

Double-click Vision Master icon in the desktop or select Start > Program > Vision Master to start the program.

# 6.4.2 Exit

Click [X] button on the top right corner of the screen or 'exit' in the file menu to end the program.



Since work group, parameter settings, and data are not saved automatically, please make sure that you have saved the work group before you exit.

Unsaved data will be lost, Do you want to save current Work Group?	Save Work Group		×
	1		
Save to the PC Save to the Device Unsave Cancel			×
		Unsave	Cancel

Vision Master - Example.avs File(F) Device(D) Help(H)	2 266 0 0 0 0 0	🔓 🚨 🔍 💭 x1.30 🔹 🗮 🕕 🔠	H 🖾 (a)	▶ ₩ 1fps • 🔞
3 Retvork Camera → ) Input [→ Output Work Group Work Group Inspection	4 VG-st VG-MOAV CE CE MADE IN KORE	V-25E         100         5: IN1           160570A         S: IN2         7: OUT0           160570A         S: IN3         9: OUT1           VSP-REMARS VG MORFW         S: S         10: OUT2           10: OUT2         11: COMMON –         11: COMMON –           200         4684         12: OUT3	Brown Blue White Green Pink Yellow Black Black Red Violet	6 /6 2.bmp 2.bmp 3.bmp 4.bmp 5.bmp
VG-M04W-16E 210.124.103.8	Network         VG-M04W-16E           Device         VG-M04W-16E           IP Address         210.124.103.8           MAC Address         58:E8:06:00:26:D1           Setting         🏠	Image Frip           ON           Server IP Address           192.168.0.1           User ID           guest           Image Format           BMP           Saved Path           Fig. 1000000000000000000000000000000000000	Port 21 Password ***** Save Opton One or More Falure	<ul> <li>Save Changes</li> <li>FTP Access Test</li> <li>Show Faled ROI</li> <li>Show Faled ROI</li> </ul>

# 6.5 Vision Master Screen Layout

The program screen is divided into sections as shown in the preceding screenshot and each section is composed of the following items.

No.	Item	Description
1	Menu	Displays Vision Master menus by category.
2	Tool bar	Displays icons of frequently used menu, settings of image window, camera snap, or etc.
3	Setting menu	Displays vision sensor setting parameter menu. If none of device of connected, it is available to connect simulator to register work group and inspection test. Activation of the setting menu depends on the type of the connected device (simulator or device) - Simulator connection: work group, inspection - Device (vision sensor) connection: network, camera, input, output, work group, inspection
4	Image window	<ul> <li>Displayed image is different according to the mode and settings.</li> <li>Setting mode: displays a taken image by vision sensor or selected image between master image to register work group and loaded image to preview window.</li> <li>Operation mode: displays taken images according to the "View Result Image" settings. Please refer to '6.6.6 Inspection'.</li> </ul>
5	Inspection result	Displays inspection result (Pass/Fail) of work group.

No.	Item	Description								
6	Preview window	Displays loaded images. If the 'Add Taken Image to Preview Window' icon ( ) is activated, preview window displays images taken by the vision sensor, which are different according to the mode and settings. - Setting mode: displays all images taken by the vision sensor. - Operation mode: while inspecting, displays taken images according to the 'View Result Image' settings. Please refer to '6.6.6 Inspection'. Right click in the preview window to display setting menu as follows. Load Image File Load Image Folder Save Selected Image E Select All Delete Selected Image								
7	Status information	Displays status information of the device and work group. - Device status : displays information of simulator or device (vision sensor) connected to Vision Master. It is available to connect or disconnect device. Indicator on the top right side enables to check the communication status between Vision Master and the device, when the device is connected. The indicator flashes while data communication. Werke Status Simulator VG-M04 VG-								
8	Parameter	Displays specific parameters in the setting menu.								
9	Image information	Displays brightness value and pixel coordinate of the point where the mouse cursor is pointing on the image window.								

# 6.5.1 Menu

File(F) Device(D) Help(H)

## (1) File

File	F) Device(D) Help(H)						
12	Open Image(O)						
2	Open All Images from Folder(F)						
≞	Save Image(S)						
6	Work Group Manager(M)						
۵	New Work Group(N)						
1	Load Work Group from PC(W)						
1	Save Work Group to PC(K)						
	Load Work Group from Device(D)						
₽	Save Work Group to Device(E)						
×	Exit(X)						
<ul> <li>Open Image: Opens the image to inspect</li> </ul>							

- Open All Images from Folder: Opens the folder of images to inspect.
- Save Image: Saves the image displayed in Image window.
- Work Group Manager: Displays a list of work group saved in the PC or device to copy, delete, or save. It is available to set work group to use when the device turns on.

뜰 Work Group List i	n PC			Work	Group List in Device		
Number	Work Group Name	Storage Time		Number	Work Group Name	Storage Time	Power On Operation
1 Ex	ample.avs	2018-5-14 10:44:48	3 🔺	▶ 1	Example.avs	2018-5-14 10:46:37	
				2	Test.avs	2018-5-14 10:49:53	©
				3			
			4 🕨	4			
				5			
				6			
				7			

No.	lcon	
1	×	Deletes selected work group.
2		Selects a folder in the PC to load work group from.
3		Copies work group from the device to the PC.
4		Copies work group from the PC to the device.
5		Selects work group to operate when the device turns on.

- New Work Group: Registers new work group.
- Load Work Group from PC: Loads work group from the local disk of PC.
   Work groups are saved in the default folder [C:\Users\ (Account name) \Documents\Autonics\Vision Master\Work] or the folder designated by user.
- Save Work Group to PC: Saves work groups registered and set in Vision Master to the local disk of PC.

Work groups are saved in the default folder [C:\Users\ (Account name) \Documents\Autonics\Vision Master\Work] or the folder designated by user.

• Load Work Group from Device: Loads work group from the device (vision sensor).

	Work Group from the device.		
Number	Work Group Name	Storage Time	Power On Operation
1	Example.avs	2018-5-14 10:46:37	
2	Test.avs	2018-5-14 10:49:53	0
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			

• Save Work Group to Device: Saves work groups registered and set in Vision Master to the device (vision sensor). Click number of work group to save to set the name of work group. At that moment, selected work group can be set as operating work group when the device turns on. Work group can be registered and saved up to 32.

ave the Wo	the Work Group							
🖓 Please	select a location to save Wor	k Group.						
Number	Work Group Name	Storage Time	Power On Operation	Т				
1	Example.avs	2018-5-14 10:46:37						
2	Test.avs	2018-5-14 10:49:53	0					
3								
4								
5								
6	Save Work Group		<b>—</b> ×					
7								
8	Work Group Name :							
9								
10	Sets as work group to operate when power On.							
11								
12	Save 🔀 Cancel							
13								
14								
15								
16								
17								
18								
19								
20								
21								

• Exit: Exits Vision Master.


# (2) Device



I/O Test: Displays input status with the indicators (no input: ) / input: ). Also it is available to set control output type (NPN/PNP) and whether use each output or not.
 I/O test is only for testing output, so that it is not associated with settings of output parameter

Input		
Input	Satus	
Trigger	•	
Input 0	0	
Input 1	•	
Input 2	•	Encoder count
Input 3		0 Pulse
(> Output		
Output	Control	Status
Output 0	NPN -	ON
Output 1	NPN -	ON
Output 2	PNP 🔻	OFF

- Firmware Update: Updates firmware version of the device (vision sensor).
- Device reset: Resets the device, deleting saved work group and set parameters from the device.
- (3) Help



- User Manual: Loads user manual.
- Language: Changes program language.
- Vision Master Update: Updates version of Vision Master.
- Vision Master Information: Displays information about version of Vision Master and device firmware.

# 6.5.2 Toolbar


12 🚔 🧯	🔓 🔞	<u>)</u>	脑 🛍	📤 🚨	0	<b>Q</b> 🔁 x1.3	0 - 🔁			🖻 🖸	M	• •	I 1fps	•	٥
1	2		3	4		5		6	7	8			9		10
Section	lcon					Descri	ption								
1	Open Image       Open All Images       from Folder				_										
				Image Group		_									
2			Manag New V	-	Group										
3			Open from F	Work G PC	roup	,	refer to '(	1) Fi	le' in	'6.5.1 Me	enu'.				
			to PC	Work Gr		_									
<b>4</b> <sup>×1</sup>			from [ Save	Device Work Gr											
	•		to Device Zoom in			Enlarge	s image.								
	Q		Zoom	out		Reduce	es image.								
5			Fit to	Window		Adjusts	the size	of th	e ima	ge to fit t	to the	ima	ge wir	ndow	·.
5	x1.31	•	Image	e Scale		Resize - Settin	image. g range:	×0.5	, ×1,	×2, ×4	I, ×8,	, ×1	6		
	E		Full S	creen			s image i off full sc button.					ey c	r dout	ole cl	ick
6			Show Bar Gauge				Displays the pass range of inspection which set in work group as bar gauge.							C	
7			Multi \ (4 cha	View annels) <sup>×:</sup>	3		s inspect ne time.	ion s	tatus	of maxir	num 4	4 vis	ion se	nsor	s at
			Snap			Takes a	an image	with	the c	amera o	f visic	on se	ensor.		
<b>8</b> <sup>×1, ×2</sup>			Contir	nuous Si	nap		nultiple ir ng to the								
9			Backv	vard		Loads <sub>I</sub>	previous i	mag	e fron	n images	s in pr	evie	w win	dow.	

Section	lcon		Description						
		Play	Loads images consecutively from images in preview						
			window.						
		Forward	Loads next image from images in preview window.						
	1fps 🔻		Selects the image playing speed for displaying images from						
		Image Play Speed	preview window.						
			- Setting range: 4fps, 2fps, 1fps, 1/ 2fps, 1/4fps						
		Pause	Pauses playing of images from preview window.						
10%1		Add Taken Image	Adda takan imagaa ta provinu windowa						
10 <sup>×1</sup>		to Preview Window	Adds taken images to preview windows.						

※1. It is not displayed in simulator operation.

 $\times$ 2. It is displayed only when the camera trigger mode is set to 'free-run trigger' or 'internal trigger'.

- X3. Use Multi View function as flows.
- 1st Click Multi View icon ( 1 to open Multi View window as flows.



# **Autonics**

2nd	Click	0	Connect	on	the top.			
	Device :	Devic	e ID / 192.1	58.0.1	/ 58:E8:08:00:00	:01		
	C	onnect				-	Pass: 0	Fail: 0


3rd Select the device to connect.


You can only select devices which of the connectable status indicator is turned on in green color.

	Please select simulator or device to connect.									
	Device	IP Address	MAC Address	Connectable staus						
	🔐 Simulators									
	品 VG-M04									
	₩ VG-C04									
	🔐 Devices									
	VG-C04W-8E	210.124.103.194	58:E8:08:00:37:36	٥						
Þ	📜 VG-M04W-16E	210.124.103.8	58:E8:08:00:26:D1	٢						
	1 VG-C04W-8E	210.124.103.246	58:E8:08:00:19:C6	۲						
	10 VG-C04W-8E	210.124.103.7	58:E8:08:00:25:ED	۰						
	10 VG-C04W-8E	210.124.103.192	58:E8:08:00:37:26	۲						
	1 VG-C04W-25E	210.124.103.189	58:E8:08:00:3A:4B	٥						

4th Set View Result Image.

Inspection result of the running device (vision sensor) is displayed in the image window. Device : VG-M04W-16E / 210.124.103.8 / 58:E8:08:00:26:D1





5th You can monitor statistics of Pass/Fail result.

6th You can monitor inspection status of maximum 4 vision sensors at the same time.



# 6.6 Setting Menu

# 6.6.1 Network



FTP			B Save Changes
ON			
rer IP Address 192.168.0.1	Port 21		FTP Access Test
ID guest	Password *****	۲	
ge Format BMP 🔹	Save Option	ne or More Failure 🔹	Show Failed ROI
ed Path ftp://192.168.0.1:21/			
Name 00000001_TEST_Pass.bmp			₿
9	ON           rt IP Address           192.168.0.1           ID           guest           e Format           BMP           +           ftp://192.168.0.1:21/	ON         pr IP Address         192.168.0.1         Port         21           ID         guest         Password         ■■■■           e Format         BMP         Save Option         Q           IP ath         ftp://192.168.0.1:21/         IP         IP	O N           Ir IP Address         192.168.0.1           ID         guest           Password         ******           ID         BMP           Save Option         One or More Failure           IP ath         ftp://192.168.0.1:21/

### (1) Network

🏪 Network	
Device	VG-M04W-16E
IP Address	210.124.103.8
MAC Address	58:E8:08:00:26:D1
Setting	\$

It is available to set vision sensor and PC network.

- Device: Displays currently connected vision sensor to Vision Master.
- IP / MAC Address: Displays IP / MAC address of the connected device.
- Setting: Changes IP address setting of the currently connected device. [Current Network Setting] is network information of the currently connected device. To change network setting, enter new information in [New Network Setting].

Device Network	X
🔒 New Networ	k Setting
IP Address	192.168.0.2
Subnet Mask	255.255.255.0
Gateway	192.168.0.1
E Current Netv	vork Setting
E Current Netv	vork Setting
IP Address	210.124.103.8
Subnet Mask	255.255.255.0
Gateway	210.124.103.1
MAC Address	58:E8:08:00:26:D1
	✓ OK X Cancel

OFF

#### (2) FTP

🔂 FTP				民 Save Changes
ON				
Server IP Address	192.168.0.1	Port	21	FTP Access Test
User ID	guest	Password	*****	FIF ACCESS TESC
Image Format	BMP	Save Option	One or More Failure	Show Failed ROI
Saved Path	ftp://192.168.0.1:21/			
File Name	0000001_TEST_Pass.bmp			

Transmits inspection result images saved in vision sensor memory to FTP server.

Select whether to use FTP function or not. (

- Server IP Address / Port: Enter IP address and port of FTP server.
- User ID / Password: Enter user ID and password.
   ※If Show Password icon ( <sup>(1)</sup>) is clicked, being entered password is displayed in characters, not '\* '.
- FTP Access Test: Checks status of connection to FTP server.
- Image format: Select image format to be saved when transmitting image to FTP server. You can select between BMP (\*.bmp) and JPG (\*.jpg).

ON /

Save Option: Sets conditions for saving images.
 All Pass: Only saves images which pass all the inspection items in work group.
 One or More Failure: Saves images which failed to pass one or more among inspection items in work group.

 $\times If$  Show Failed ROI check box is checked, ROI which failed to pass inspection is marked in the result image.

- Saved Path: Enter location in server to save the result image.
   When designating folder to upload, click 'Upload Folder Path' icon ( 2000) on the right side. You can see the list of folder in the server.
- File Name: Sets file name of image to transmit to the FTP server. Click 'Image File Naming Rule' icon ( ) on the right side to set name.

# **Autonics**

# Note

Image file naming rule is as flows.

Item can be set up to 5, and you can customize the order of the items.

Image File N	Jaming Rule
ltern 1 :	Image Number
ltern 2 :	Image Name   TEST
ltern 3 :	Inspection Result 🔻
ltern 4 :	Work Group Number
ltern 5 :	Work Group Name
Example	00000001_TEST_Pass_01_Example.bmp 1 2 3 4 5 6
	✓ OK Cancel

- Image Number: It is number of taken image. It is necessary for image file naming.
- Image Name: User can set image name using only Korean, English alphabet, number, and some of special characters (except " < > ? \* / \ |)
- Inspection Result: Displays inspection result of Pass/Fail.
- Work Group Number / Work Group Name: Displays number and name of inspecting work group.
- Image format filename extension: It is image format filename extension. It displays BMP (\*.bmp) or JPG (\*.jpg).

# 6.6.2 Camera



😘 Camera			E, Sa	ave Changes
Trigger Mode		Parameter Calibration		-
External Trigger	•	Exposure Time(µs)	1000	
Trigger Delay Mode Disable	-	Exposure Delay Time(µs)	30	
obdole		Frame per Second(fps)		
		Gain		
		Light		ON 🥥
			Till, Focusi	ng Guide

# 6.6.2.1 Trigger

😘 Camera	
Trigger Mode	
External Trigger	•
Trigger Delay Mode	
Disable	•

## (1) Trigger mode

-

- Free-Run trigger: Takes images with the maximum trigger speed that can occur in the sensor. (fixed to 60fps)
- Internal Trigger: Takes image by occurring trigger in the sensor (1 to 60fps)
- External Trigger: Takes image with external input signal as trigger. If you use external trigger mode, you can use trigger delay mode.

# (2) Trigger Delay Mode

Trigger Mode				
External Trigger	•			
Trigger Delay Mode				
Encoder	-			
Disable			Trigger Delay Mode	
Time			Time	-
Encoder				_
			0	ms
L		_	Trigger Delay Mode Encoder	-


Trigger delay means delayed time from inputting moment of external trigger to actual starting moment of image taking.

- Time: Sets the trigger delay in time unit. Setting range is from 0 to 60,000ms.
- Encoder: Sets the trigger delay in unit of the number of pulse. Setting range is from 0 to 16,000,000 pulses.

Click 'Encoder Delay Pulse Calculator' ( **1**) and enter moving distance and distance resolution of encoder to calculate pulse value according to um/pulse or pulse/um setting value.



After setting the trigger delay mode, timing diagram of trigger input is shown as follows.




## 6.6.2.2 Parameter

Parameter Calibration						
Exposure Time(µs)	1000	-				1
Exposure Delay Time(µs)	30					1
Frame per Second(fps)	1					1
Gain	1					1
Light	1					ON
					Focusing	g Guide

#### (1) Exposure time

Exposure time is the time span for which the vision sensor is exposed to the light. The longer exposure time is, the brighter the taken image is, and the shorter exposure time is, the darker the taken image is.



#### (2) Exposure delay time

Exposure delay time delays the light receiving point of vision sensor. Setting range is from 30 to 10,000us.

#### (3) Frame per second

Frame per second is Frame rate which is the number of images taken per 1 second. It is settable only when the trigger mode is set to "internal trigger". Setting range is from 1 to 60fps.

%In the external trigger mode, the vision sensor takes images with external input signal, so that you cannot set the frame per second.


XIn the free-run trigger mode, the vision sensor takes images at the fastest speed which the vision sensor can.

(The shorter exposure time is, the faster the vision sensor can take.)

#### (4) Gain

It is adjusting gain of CMOS image sensor.

As higher gain level makes image brighter, increased noises makes resolution low. Setting range is from the level 1 to 16.



OFF 🥥

CE ROHS RI

## (5) Light

You can set whether to use inner LED light or not. (Use: \_\_\_\_\_ /not use: \_\_\_\_\_

Setting range is from the level 1 to 16.

 Light level 1
 Light level 8
 Light level 16

 VG SERIES
 VG SERIES
 VG SERIES
 VG SERIES

 Register on Widdh Status Statement
 VG SERIES
 VG SERIES
 VG SERIES

 Register on Widdh Status Statement
 VG SERIES
 VG SERIES
 VG SERIES

 Register on Widdh Status Statement
 VG SERIES
 VG SERIES
 VG SERIES

 Register on Widdh Status Statement
 VG SERIES
 VG SERIES
 VG SERIES

 Register on Widdh Status Statement
 VG SERIES
 VG SERIES
 VG SERIES

 Register on Widdh Status Statement
 VG SERIES
 VG SERIES
 VG SERIES

 Register on Widdh Status Statement
 VG SERIES
 VG SERIES
 VG SERIES

 Register on Widdh Status Statement
 VG SERIES
 VG SERIES
 VG SERIES

 Register on Widdh Status Statement
 VG SERIES
 VG SERIES
 VG SERIES

 Register on Widdh Statement
 VG SERIES
 VG SERIES
 VG SERIES

 Register on Widdh Statement
 VG SERIES
 VG SERIES
 VG SERIES

 Register on Widdh Statement
 VG SERIES
 VG SERIES</t

### (6) Focusing guide

Focusing guide makes adjusting image focus with the focus adjuster convenient. After setting ROI of the sensing target and checking the focusing guide value, rotate the focus adjuster to the point where the focusing guide value is the highest and fix it at the point to use.

CE Rons



How to adjust focus with focusing guide.

CEO

1st Click focusing guide button.

Focusing guide ON( Focusing Guide ) /OFF ( Focusing Guide )

2nd In the image window, the focusing guide value and area is displayed on the master image. Adjust the area to focus on. The higher the focusing guide value is, the clearer focus on the image is.



- 3rd Click continuous snap (**[]**) on the toolbar on the top.
- 4th Checking consecutively taken images, rotate the focus adjuster to the FAR or NEAR direction. Since initial setting is unknown, rotate the focus adjuster to both FAR and NEAR directions and fix the adjuster at the point where the focusing guide value is the highest.



When sensing target is in near	Focus adjusting is finished.	When sensing object is far
$\rightarrow$ rotate to the NEAR		$\rightarrow$ rotate to the FAR direction.
direction.		
Autonics memory i service	Autonics SENSORS & CONTROLLERS	84 Autonics SENSORS & CONTROLLERS


### 6.6.2.3 Calibration

Parameter Calibrat	ion						
Actual Measureme	ent		ON	Approx. Measure	ement		OFF
Pixel Distance	0	0		Focal Length	8	▼ mm	
Edge Threshold A	40			Working Distance	0	μm	
Edge Threshold B	40						
Actual Distance	0	μm					
				1 Pixel = 0 µm		🔗 ОК	

Calibration has two method of 'actual measurement' and 'approximate measurement'. Since those methods cannot be set at the same time, you have to select one method of them.

Claibration calulates  $\mu m$  per 1 pixel to register.

Since the vision sensor measures distance in unit of pixel, use calibration function for calculating in unit of  $\mu$ m.



# (1) Actual measurement

- Pixel Distance: It displays distance between edge A and edge B in pixel.
- Edge Threshold A/B: It is for setting edge threshold to detect edge.
   With the higher edge threshold value, edge of high contrast is detected, and with the lower edge threshold value, edge of low contrast can be also detected.
- Actual Distance: It is for entering actual distance between two edges in unit of  $\mu$ m.

After setting the edge threshold value and entering the actual distance, click 'OK' ( $\checkmark \circ \infty$ ) in the right bottom corner to register values after calculating distance per 1 pixel into unit of  $\mu m$  based on the set values in 'Actual Measurement' tab.

Parameter Calibrati	ion						
Actual Measureme	ent		ON	Approx. Measure	ement		OFF
Pixel Distance	233			Focal Length	8	▼ mm	
Edge Threshold A	40			Working Distance	0	μm	
Edge Threshold B	40						
Actual Distance	39670	μm					
				1 Pixel = 170 µm		🔗 ОК	

#### (2) Approximate measurement

Approx. Measure	ement	ON
Focal Length	8 🗸	mm
Working Distance	0	μm

- Focal Length: It is for selecting effective focal length of the connected device (vision sensor).
- Working Distance: It is for entering distance between sensing target and the vision sensor.

After selecting focal length and entering the working distance, click 'OK' ( $\checkmark$ ) in the right bottom corner to register values after calculating distance per 1 pixel into unit of  $\mu$ m based on the working distance and FOV by effective focal length.

Parameter Calibration				
Actual Measurement	OFF	Approx. Measure	ement	ON
Pixel Distance 0	1	Focal Length	8	▼ mm
Edge Threshold A 40		Working Distance	650000	μm
Edge Threshold B 40				
Actual Distance 0 µm				
		1 Pixel = 388 µm		🔗 ОК

# 6.6.3 Input

-		
Input		🔁 Save Chan
Input Input	Input Mode	😫 Save Chan Active Level
	Input Mode	
Input		Active Level
Input Trigger	Camera Trigger	Active Level
Input Trigger Input 0	Camera Trigger Work Group Change - Clock	Active Level اللهم اللهم اللهم

## (1) Input mode

- Trigger input (TRIG): The selected trigger mode which set in the camera menu is the image taking signal.
- Work group change (IN0 to IN3)

- Serial input (IN0, IN1): Input 0 and input 1 are set to work group change – Clock or work group change – Data, and work group is changed according to the serial input.

- Parallel input (IN0 to IN3): From input 0 to input 3 are set to each of work group change bit 0 to 3, and work group is changed according to the parallel input.

• Encoder input (IN2, IN3): After input of trigger signal, the vision sensor takes image after waiting for a while according to the number of encoder pulse. The types of encoder input consist of Up counter/Down counter, and Quadrature. Encoder input is used for the trigger delay mode. Maximum 100kHz input can be recognized.

## (2) Active level

According to the active level, trigger is applied at High or Low. To avoid chattering of trigger signal, the vision sensor starts taking an image when the signal is maintained for 1ms.

# 6.6.3.1 Input mode

Input	Signal	Function					
0	IN0	Work group change Bit 0	Work group change - Clock				
1	IN1	Work group changeWork group changeBit 1- Data					
2	IN2	Work group change Bit 2	Encoder - Up counter - Quadrature A	Alarm cleared			
3	IN3 Work group change Bit 3		Encoder - Down counter - Quadrature B				

# (1) Work group change – parallel input (IN0 to IN3)

→) Input		民 Save Changes	
Input	Input Mode	Active Level	
Trigger	Camera Trigger 🔹	JTL High	•
Input 0	Work Group Change Bit 0	JTL High	-
Input 1	Work Group Change B≹ 1 ▼	JL High	•
Input 2	Work Group Change Bit 2	ப Low	•
Input 3	Work Group Change Bit 3	T Low	+

According to the parallel input, work group is changed.

With parallel input, work group from 1 to 16 can be changed to.

(Following table is based on the High active level.)

Input Work group	Bit 3 (IN3)	Bit 2(IN2)	Bit 1(IN1)	Bit 0(IN0)
Work group 1	Low	Low	Low	Low
Work group 2	Low	Low	Low	High
Work group 3	Low	Low	High	Low
Work group 4	Low	Low	High	High
Work group 5	Low	High	Low	Low
Work group 6	Low	High	Low	High
Work group 7	Low	High	High	Low
Work group 8	Low	High	High	High
Work group 16	High	High	High	High

# (2) Work group change – serial input (IN0, IN1)


Input		E.	Save Changes
Input	Input Mode	A	ctive Level
Trigger	Camera Trigger ·	JTL High	•
Input 0	Work Group Change - Clock	JL High	•
Input 1	Work Group Change - Data	JL High	•
Input 2	Disable	ՂՐ Low	•
Input 3	Disable ~	℃ Low	-

According to the serial input, work group is changed.

Although data is 8-bit, 5 less significant bits are used, because the maximum number of work group is 32.

Input	Bit 0	Bit 1	Bit 2	Bit 3	Bit 4	Bit 5	Bit 6	Bit 7
Work group								
Work group 1	0	0	0	0	0	0	0	0
Work group 2	1	0	0	0	0	0	0	0
Work group 3	0	1	0	0	0	0	0	0
Work group 4	1	1	0	0	0	0	0	0
Work group 5	0	0	1	0	0	0	0	0
Work group 32	1	1	1	1	1	0	0	0

With serial input, work group from 1 to 32 can be changed to.



- Start bit: Start bit holds the data signal at Low (Falling edge) for 20ms.

- Clock bit: Clock bit is pulse of 20ms interval which acquires data at the Rising edge.

- Data bit: Data bit is synchronized with Falling edge of the clock signal and holds Low or High for 20ms.

- End bit: After 8<sup>th</sup> data, end bit holds the data signal for 20ms.

# Ex.

When changing work group of the vision sensor to work group 6 with the serial input signal, input the data signal as follows.

Data								
Input Work group	Bit 0	Bit 1	Bit 2	Bit 3	Bit 4	Bit 5	Bit 6	Bit 7
Work group 6	1	0	1	0	0	0	0	0

## (3) Encoder input

You can use encoder input when you want to use the trigger delay mode of external trigger input on encoder pulse.

Camera trigger occurs after calculating moving distance according to the number of input pulse.

Input					
Input	Input Mode	A	Active Level		
Trigger	Camera Trigger 🗸	JL High			
Input 0	Disable	JL High			
Input 1	Disable	JL High			
Input 2	Encoder - Up counter	ு Low			
Input 3	Encoder - Down counter	T Low			


Input 2 and input 3 are used as each of encoder input up counter and down counter. The number of pulse is counted up or down according to the active level. If you use only one encoder input, connect unusing input terminal to COMMON. Rising edge is counted in the high active level, and falling edge is counted in the low active level.

Encoder Up Count					
	4	3	2	1	
Encoder Down Count					

• Quadrature A/Quadrature B (IN2, IN3)


🕽 Input		B	Save Changes
Input	Input Mode	A	Active Level
Trigger	Camera Trigger -	JL High	
Input 0	Disable	JL High	
Input 1	Disable	JTL High	
Input 2	Encoder - Quadrature A	ி Low	
Input 3	Encoder - Quadrature B	T Low	

Input 2 and input 3 are operated in encoder Quadrature. Both rising edge and falling edge of two encoders are counted.



# (4) Alarm cleared

You can use the alarm cleared input to cleare alarm which is set in the output menu, when alarm is ON. Although alarm is cleared, alarm occures again in the status at alarm condition which is set in the output menu,



# 6.6.4 **Output**




€→ Output										B	Save Changes
Output		Output Mode			Control	Output		Pulse Type	Duration(ms)	Delay Type	Delay Time(ms)
Output 0	Disable		•	NPN	•	Л. N.O.	•	Latch 🔹	10	After Inspectio 👻	0
Output 1	Insepction Result		•	NPN	•	JL N.O.	•	Pulse 🔻	10	After Trigger I 🔻	17
Output 2	Inspection Complete		•	NPN	•	JL N.O.	•	Pulse 🔻	10	After Inspectio	0
Output 3	Alarm	<ul> <li>FTP File Transmission Error</li> </ul>	•	NPN	•	JL N.O.	•	Latch 🔻	10	After Inspectio *	0


### (1) Output mode

Output Mode	
Disable	•
Disable	
Inspection Completed	
Inspection Result	
External Light Trigger	
Alarm	
Camera Busy	
Changing Work Group Completed	

- Inspection Complete: Regardless of the inspection result, the vision sensor outputs output signal at the moment of inspection completion.
- Inspection Result: According to the settings of Output Inspection Result Selection, the vision sensor outputs output signal. Please refer to '6.6.5 Work Group'.



 External light trigger: When connected with the external light, power of the external light is turned ON/OFF with output signal from the vision sensor which is synchronized with camera trigger input.




• Alarm: In occurrence of vision sensor error, the vision sensor outputs output signal.

Output Mode

Output Mode	
Alarm 👻	<b>T</b>
Disable	Trigger Input Error
Disable	Calculation Time Exceeded Work Group Change Error
Disable	FTP File Transmission Error
т <u> </u>	OK Cancel

Alarm output	Description				
Trigger input error	When trigger is input in high camera busy signal, the vision sensor outputs alarm.				
Operating time exceeded	When operating time of work group is exceeded set inspection time, the vision sensor outputs alarm.				
Work group change error	When unregistered work group number is entered or wrong Clock or Data is input in serial or parallel input, the vision sensor output alarm.				
FTP file transmission error	When FTP access error or FTP transmission error in saving inspection result occurs, the vision sensor outputs alarm.				

• Camera busy: It is operating status of the camera, after camera trigger input.



• Changing work group completed: It is signal to notice that changing work group is completed after inputting work group change input.

Work Group Change Input	<u></u>
Work Group Change process	
Work Group Change Completed Output	

#### (2) Control output

Control Output						
NPN	-	Л. N.O.	•			
NPN		Л N.O.				
PNP		Ъ N.C.				
NPN	•	JEN.O.	-			
NPN	-	Л. N.O.	-			

You can set control output to NPN/PNP and N.O.(Normally open) / N.C(Normally close).

#### (3) Pulse type


You can select pulse type for output. You can select pulse type only when the output mode is set to 'Inspection complete', 'Inspection result', or 'Alarm'.

- Pulse: Output signal is output during set output duration.
- Latch: Output signal is kept outputting before next output signal.

#### (4) Duration

Duration is the time period of maintaining inspection result output signal for. You can set duration by setting output mode to "Inspection result" and pulse type to "Pulse". Setting range is from 1 to 60,000ms.


• Timing diagram of output duration (ms).



#### (5) Delay type

Delay type is the moment of applying output delay time to. You can set whether to delay output after inspection completed or to delay output after trigger input.

• Delay output after inspection completed



#### (6) Delay time

Delay time is the time period of delaying inspection result output for, after starting of output delay operation.

- Setting range when delay type is "After inspection completed": 0 to 60,000ms
- Setting range when delay type is "After trigger input": 17 to 60,000ms

### 6.6.5 Work Group




W	ork List					ີ la Output 0 Inspection Res	sult		Logic Comb	ination
Nu	umber	Work	Result	Add		Logic Output			Logic Option	Result
	1	Alignment 1	Pass *		•	CE THE			! NOT	🝷 🥝 Pass
	2	Brightness 1	Pass	📝 Edit		✓ I OR			-	Pass
	3	Contrast 1	Pass			🔆 Brightness :	L		-	Pass
	4	Area 1	Pass	Delete		Contrast 1			-	Pass
	5	Edge 1	Pass			- & AND			-	Pass
	6	Length 1	Pass	🗍 Delete All	⊩	Length 1			-	Pass Pass
	7	Angle 1	Pass			Lenger 1				- P 835
	8	Diameter 1	Pass							
	9	Object Counting 1	Pass -	🖂 Change Master Image		Output0	Output1	Output2		Output3

#### (1) Work list

	Number	Work	Result	Add
Ì		Alignment 1	🙆 Pass 🔶	
ſ	2	Brightness 1	Pass	📝 Edit
	3	Contrast 1	Pass	
	4	Area 1	Pass	😑 Delete
	5	Edge 1	Pass	
	6	Length 1	Pass	m Delete All
	7	Angle 1	Pass	
	8	Diameter 1	Pass	
	9	Object Counting 1	Pass -	[ 🚑 Change Master Imag

Work list displays a list of the currently registered works and you can register work to inspect and edit or delete the registered works in Work list.

• Add: You can register work to inspect. Select inspection type and register. When making new work group and adding work, an image in the image window is registered ads master image.



#### Please refer to '6.7 Inspection ' for inspection item setting.

Alignment Presence Measurement Color	Alignment Presence Measurement Color
Rignment - calibrates position and rotation of the registered object.	- Brightness - checks the mean brightness of the object.
	Contrast - checks the contrast of the object.
	🔊 Area - checks the area of the object.
	Edge - checks the presence of the edge.
	Shape comparison - inspects the shape of the object.
Alignment Presence Measurement Color	Alignment Presence Measurement Color
→ Length - measures the length between the two edges.	Solor identification - checks the average color of the object.
Angle - measures the angle between the two edges.	Area of color - checks the area of color.
↔ Diameter - measures diameter of the circle object.	$\overset{oldsymbol{0}}{\overset{\ble}{oldsymbol{$
$\bigotimes_{OO}$ Object counting- counts the number of objects.	

- Edit: Select the registered work in the list and click Edit to edit the work.
- Delete / Delete All: Select the registered work in the list and delete a work or delete all works.

Change master image: You can change image template of the work to register. The currently displayed image in the image window is registered as master image.



You can copy and paste registered works in the work list by using Ctrl+C and Ctrl+V.

It is except for Alignment 1 work.

1st Select a work to copy, and press Ctrl+C key to copy.

e		.) Brig Work List	htness 1			1
				1		
		Number	Work	Result	🔿 Add	
		1	Alignment 1	Pass		
	۲	2	Brightness 1	Pass	📝 Edit	
		3	Area 1	Pass		
		4	Angle 1	Pass	😑 Delete	
		5	Length 1	Pass		
					🗍 Delete All	
					🔄 Change Master Image	
2nd E	Dre	ee Cti	rl+V key to open tl	ha massada n	on-un as helow a	nd click 'OK'
		by Work	The Rey to open ti		op-up as below, a	na choix orx.
	Cop	by work				
		2 Do	you want to copy the work? (B	rightness 1)		
			ОК	Cancel		
			in nominal			
3ra I			is copied.			1
		Work List				
		Number	Work	Result	Add	
		1	Alignment 1	Pass		
		2	Brightness 1	Pass	📝 Edit	
		3	Area 1	Pass		
		4	Angle 1	Pass	😑 Delete	
		5	Length 1	Pass		
	۲	6	Brightness 2	Pass	🔟 Delete All	
					🔄 Change Master Image	

4th Select the copy of the work and click 'Edit' to change specific settings of the work.

#### (2) Output inspection result selection

ੈਫ਼ Output 0 Inspection Res	ult		Disable 🔹
Logic Output		Lo	gic Option desult
🕨 👻 🕹 AND		1	NOT 🔻 💎 Pass
-   OR			Disable
🔆 Brightness 1			All Pass
Contrast 1			One or More Failure Alignment
- & AND			Logic Combination
🔊 Area 1			- Pass
Length 1			- 🕘 Pass
	1		
Output0	Output1	Output2	Output3

Set output mode in output menu to "inspection result" and set outputting condition among followings.

- Disable
- All pass: When all of inspection results are passed, the vision sensor outputs output signal.
- One or more failure: When one or more inspection result is failed to pass, the vision sensor outputs output signal.
- Alignment: When inspection items with alignment are passed, the vision sensor outputs output signal.
- Logic combination: You can set output conditions by setting each logic combination to pass or fail with logical operator.

Note

When setting output with logic combination, set output condition using logical operator for each output.

ីខ្លែ Output 0 Inspection Result		Logic Combi	nation 🔹	
Logic Output		Logic Option	Result	
- 🕹 AND		! NOT	🔹 🥝 Pass	
- I OR		-	Pass	
Brightness 1		-	Pass	
Contrast 1		-	Pass	
- & AND		-	Pass	
Area 1		-	Pass	
🕁 Edge 1		-	Pass	
Output0	Itput1 Output2		utput3	3
OR	AND	]		
Invert None	Invert None			
Invert All	Invert All			
Delete All	Delete All	& AND		
Add Logical Operator	Add Logical Operator	OR		
Add Work 🕨	Add Work	🕒 🗷 Alignme	nt 1	Delete W
	-			
		Contrast		
		👌 Area 1		
		🕁 Edge 1		
		Length 1		
		Angle 1		
			- 1	
		<ul> <li>Diamete</li> </ul>		
		🛞 Object C	counting 1	

- AND/OR: You can select logic operator.
- Invert none: You can set logical option of all work to NONE(-).
- Invert all: You can set logical option of all work to NOT.
- Delete all/Delete logical operator: You can delete all registered settings of with Delete all and registered logic operator with Delete logical operator.
- Add logical operator: You can add logical operator (AND/OR).
- Add work/Delete work: You can add registered work to logical output or delete work from logical output.

## 6.6.6 Inspection

	$\bigcirc$									
Devic	ce			tion Status					Reset St	tatistics
			Number	Work Name	Result Value	Result	Pass/Fail	Operating Time(ms)	- Input Trigger	9.9%
	Start Device Inspection					-				
			1	Alignment 1	91 [X:387 Y:250 R:-0.1]	0	352/8(97.7%)	589.25	Pass	360
liow Por			1	Alignment 1 Brightness 1	91 [X:387 Y:250 R:-0.1] 155	<b>0</b>	352/8(97.7%) 331/29(91.9%)	589.25	Pass Fail	360 3274
	ult Image		1 2 3					0		3274
	ult Image	<b>*</b>		Brightness 1	155	٢	331/29(91.9%)	0.20	Fail	3274
	ult Image 25 - 3 Alarm - 4		3	Brightness 1 Contrast 1	155 68	0	331/29(91.9%) 344/16(95.5%)	0.20 1.03 0.36	Fail - Work	3274 57.2%
All Image	ult Image as Alarm Q Inspection Result Q		3	Brightness 1 Contrast 1 Area 1	155 68 3058	0	331/29(91.9%) 344/16(95.5%) 345/15(95.8%)	0.20 1.03 0.36	Fail - Work All Pass	3274 57.2% 206
All Image 0 1 2	ult Image as Alarm Inspection Result Inspection Complete		3 4 5	Brightness 1 Contrast 1 Area 1 Edge 1	155 68 3058 0 [Distance:3]		331/29(91.9%) 344/16(95.5%) 345/15(95.8%) 296/64(82.2%)	0.20 1.03 0.36 9.80	Fail - Work All Pass One or More Failure	3274 57.2% 206 154
All Image 0 1	ult Image as Alarm Q Inspection Result Q		3 4 5	Brightness 1 Contrast 1 Area 1 Edge 1 Length 1	155 68 3058 0 [Distance:3] 364	0 0 0 0	331/29(91.9%) 344/16(95.5%) 345/15(95.8%) 296/64(82.2%) 331/29(91.9%)	0.20 1.03 0.36 9.80 20.41	Fail - Work All Pass One or More Failure The Number of Works	3274 57.2% 206 154 9

#### (1) Device

 Start/Stop device inspection: You can activate vision sensor in operation mode and start inspection in registered work group.

$\checkmark$	Start Device	Inspection

Stop Device Inspection

View result image: You can set image to display in the image window during inspection. View Result Image

Disable Passed In Failed Ima All Image	age	0
2	Inspection Complete	
3	Disable	0

• Save result image: Click the 'Save result image' icon ( ) on the right side in View result image. You can set the result image in local disk of the PC.

Save Re	sult Image			×
2 Imag 3 Save	e Result Image ge Format ed Path age Space Setting	ON BMP C:₩Users₩Administrator₩Documents₩Auto	nics₩Vision Master₩Image∜ 100	▼ ▲ MByte
	age Space Usage a Free Space	The number o	f files : 0 0 74755	MByte MByte X Cancel
	1 14			Cancer
No.	Item	Description		Cancer
<b>No.</b> 1	Item Save result i			
		nage Sets whether to save in	spection result image.	

No.	Item	Description
4	Storage space	Charles drive free energy and allocated anone to accur
4	setting	Checks drive free space and allocates space to save.
F	Storage space	Displays the number and volume of the files in storage anone
5	usage	Displays the number and volume of the files in storage space.
6	Drive free space	Displays drive free space of the PC.


• Output status: Output status displays output status during inspection. You can check output mode and operation status of output.

0	Alarm	0
1	Inspection Result	<b>O</b>
2	Inspection Complete	0
3	Disable	0




Please refer to followings when clicking Start device inspection to activate operation mode.

 Select operation mode: It is to set operation when starting inspection. You can select whether to save or not to save before starting inspection. When the device is turned off, you can lose unsaved data.



Setting of displaying the inspection image in full screen



#### (2) Inspection Status

Number	Work Name	Result Value	Result	Pass/Fail	Operating Time(ms)		- Input Trigger	2.3%
1	Alignment 1	82 [X:377 Y:250 R:0.2]	0	103/0(100.0%)	562.72	1	Pass	103
2	Brightness 1	153	٢	78/25(75.7%)	0.19		Fail	4352
3	Contrast 1	69	0	87/16(84.4%)	1.02		- Work	46.6%
4	Area 1	5179	0	87/16(84.4%)	0.37		All Pass	48
5	Edge 1	0 [Distance:8]	0	94/9(91.2%)	9.63		One or More Failure	55
6	Length 1	0	0	89/14(86.4%)	0.82	1	The Number of Works	9
7	Angle 1	100	0	100/3(97.0%)	23.00		Overall Inspection Time(ms)	728
8	Diameter 1	68 [Round:88]	0	100/3(97.0%)	86.24	<b>T</b>		
				817/110(88.1%)	694.26			

- Work name: Displays work name of inspection items.
- Result value: Displays measured result value of each work ROI.
- Result: Displays pass/fail for inspection result.
- Pass/Fail: Displays counting of the number of pass/fail and pass rate.
- Operation time: Displays operation time of each inspection item.
- Input trigger: Displays statistics of input trigger. It helps you to check input is operating in normal status by counting the number of pass/fail status of input trigger.
- Work: Displays statistics of work. It displays the number of inspection result of All pass, One or more failure, the number of total work, and inspection time.



-

When operating device inspection with calibration function, result value of the 'edge', 'length', and 'diameter' inspections are displayed as actual value in the unit of mm, not pixel.

•	Inspection result value without calibration function	
---	--	--

	Number	Work Name	Result Value	Result	Pass/Fail	Operating Time(ms)
Þ	1	Edge 1	86 [Distance:1]	0	157/41(79.2%)	11.95
	2	Length 1	198	0	166/32(83.8%)	19.27
	3	Diameter 1	261 [Round:86]	0	160/38(80.8%)	157.27
					483/111(81.3%)	-
าร	spectio	n result value with	calibration function		483/111(81.3%)	-
าร	spectio	n result value with Work Name	calibration function Result Value	Result	483/111(81.3%) Pass/Fail	- Operating Time(ms)
ns				Result		Operating Time(ms)
	Number	Work Name	Result Value		Pass/Fail	


## 6.7 Inspection

lcon	Function	Description
	Alignment	To align position and orientation of the target based on the registered target
	Brightness	To inspect average brightness of the target
	Contrast	To inspect average contrast of the target
0	Area	To inspect area of the target
$\mathbf{x}$	Shape comparison	To inpect shape of the target
 ↓	Edge	To inspect the presence of the edge
∻≕	Length	To inspect the length between two edges
× ↑	Angle	To inspect the angle between two edges
<b>~ &gt;</b>	Diameter	To inspect diameter of the circle
	Object counting	To count the number of the object
\$	Color identification	To inspect average color of the object
	Area of color	To inspect area in a certain color
() () ()	Object of color counting	To count the number of objects in a certain color

## 6.7.1 Alignment

You can use the alignment function to align position and orientation of the target based on the registered target.

Alignment compares features of the registered target and features of the input image to figure out location of similar pattern, and then inspects the input image based on location and rotation angle of the target. It is used to check the presence of inspection target to rotate, to inspect pattern, or to align position of the target.



No.	item	Description
1	Similarity	It is the similarity between registered template and detected template.
2	Similarity threshold <sup>≋1</sup>	It is discrimination value of the similarity for deciding pass/fail.
3	Edge threshold	It is threshold to detect edge. Only edges with high contrast can be detected in high edge threshold, while edges with low contrast also can be detected in low edge threshold.
4	Edge type	It limits amount of information according to the edge direction. - Curve: It leads pixels from all edges. - Straight: It leads pixels only from straight edge.
5	Edge contrast	<ul> <li>It limits amount of edge information according to the contrast value.</li> <li>High: It uses edges of high contrast.</li> <li>Medium: It uses edges of high and medium contrast.</li> <li>Low: It uses edges of high, medium, and low contrast.</li> </ul>
6	Rotation angle range (±°)	It limits detecting area to the set angle range, by setting angle range of the rotated image to detect.
7	Automatic teaching	It operates teaching automatically, when user changes parameter or adjust ROI.
8	ROI type	After setting ROI ( <b>Template</b> ), set area ( <b>Search</b> ) to inspect ROI in it.

No.	item	Description		
		It sets type of ROI ( Templets) to inspect.		
		RECTANGLE		
		O POLYGON		
		O CIRCLE (rectangle/polygon/circle)		
9	OK/Cancel	It registers work to work group or cancel to register.		

%Threshold is the boundary value when a value is discontinuously changed.


 $\times$ 1. When set template of ROI is 50% similar with the input image in 50 similarity threshold, the vision sensor regards them as the same target and outputs output signal.





Examples of pass/fail in the alignment inspection

Registering template of inspection target (similarity: 100% / similarity threshold: 80%)



Passed alignment inspection.



Failed alignment inspection.







🖉 Note

When inspecting inspection items including alignment, alignment is prior to any other inspection items, so that rotating inspection target by alignment also rotates position of other inspection items.

Information	x
Alignment is registered as a first work.	
ОК	

If you want to apply alignment to each inspection, check 'Apply alignment' in the right bottom.

Apply Alignment					
V X	V Y	🗸 R			

X: moving X axis coordinate / Y: moving Y axis coordinate / R: angle

Examples of pass/fail when inspecting multiple work including alignment

Registering template of the inspection target (registering alignment)



Applying alignment




Unapplying alignment



## 6.7.2 Brightness

You can use the brightness function to inspect average brightness of the target.

Brightness compares mean brightness of the registered ROI and that of input image ROI. It sets pass range based on the mean brightness value of the registered ROI. The mean brightness value of the inspection target within the pass range is regarded as Pass, while the mean brightness value of the inspection target out of the pass range is regarded as Fail.




No.	Item	Description		
		It sets the pass/fail range of brightness.		
1	Pass range	166 181		
		Lower limitROI meanUpper limitfor passbrightness valuefor pass		
2	Automatic teaching	Even if user set the pass range, it teaches pass range based on mean brightness of ROI.		
3	ROI type	It sets type of ROI to inspect.  RECTANGLE  POLYGON  CIRCLE  CONCENTRIC_CIRCLE  (rectangle/polygon/circle/concentric circle)		
4	OK/Cancel	It registers work to work group or cancel to register.		





Examples of pass/fail in the brightness inspection

 Registering template of the inspection target (mean brightness: 181 / pass range: 166 to 196)




Passed brightness (alignment applied)






Failed brightness



(Reduced ROI area brightness)



(Below mean brightness of ROI area)

## 6.7.3 **Contrast**

You can use contrast function to inspect average contrast of the target.

Contrast is amount of gap between bright part and dark part in the image.


Contrast compares registered ROI contrast and ROI contrast of the input image to figure out changes in contrast. It sets pass range based on the registered contrast value of ROI. The contrast value of the inspection target within the pass range is regarded as Pass, while the contrast value of the inspection target out of the pass range is regarded as Fail. The contrast value is displayed in the percentage.

Sision Mas	ster - NewWork.avs*						
File(F) De	evice(D) Help(H)	6440	월 월 월   ☆ ♣   <b>Q, Q, (□</b> x1.30 → (□)   <b>11</b>   <b>11</b>	(a)	H > > Ifps v		
					-/-		
1	Network						
	<b>C</b>						
	Camera						
	→] Input						
	[→						
	Output						
	Ē						
W	/ork Group		Autoni	CS			
Tr	nspection		ACICI				
			-	-			
Device S		Contrast Parameter					
	avice 3-M04W-16E	Pass Range 59		74	89 🚱 Automatic Teaching		
21	0.124.103.8				ROI Type RCTANGLE		
Work Gr	Disconnect						
[ UNSAVED ] NewWork.a							
<changed:< th=""><th>&gt;</th><th></th><th></th><th></th><th>V OK</th></changed:<>	>				V OK		
(X: 1, Y:	16) Brightner	ss: 255					
<u></u>							
No.	Item		Description				
			It sets the pass/fail range	of contrast.			
_	_		59	74	▽ 89		
2	Pass r	ange	Lower limit	ROI	Upper limit		
			for pass	average contrast	for pass		
			-	-	-		
3	Autom						
Ŭ	teachir	ng average contrast value of ROI.					
			It sets type of ROI to insp	pect.			
4	ROI ty	pe					
			D POLYGON				
				(rectangle/polygon/circ	le)		
5	OK/Ca	ncel	It registers work to work	group or cancel to register			
5				group of cancer to register	•		



Examples of pass/fail in the contrast inspection

Registering template of the inspection target (contrast: 74 / pass range: 59 to 89)



#### 6.7.4 Area

You can use the area function to inspect area of the target.

Area compares difference between registered ROI area and ROI area in the input image. It sets the pass range based on the registered ROI area. The area of the inspection target within the pass range is regarded as Pass, while the area of the inspection target without the pass range is regarded as Fail.

	5*		
File(F) Device(D) Help(H	)) 🖉 🚔 🖆 🖄 🖄 🖆 🍙 📥 🖉 🔍 🔍 💭 x1.30 🕞 🗐 🛄 🔜	(8) 🗊	H ▶ ▶ 1fps - 🚺
Network Camera			4-
→] Input			
<b>[→</b> Output			
Work Group			
Inspection			
🕄 Davina Status	Area Parameter		
Device Status     Device     Verice     Verice     Verice     Verice     210.124.103.8	Area Parameter Pass Range 11301 Bray Threshold 126 Extraction Mode Dark on sight	~	15290 Q Automatic Teaching ROI Type O CIRCLE

No.	ltem	Descripti	on			
		It sets the pass/fail range of area.				
1	Pass range	Lower limit for pass	t Measured R area value	•••••••••••••••••••••••••••••••••••••••		
2	Binary threshold	It sets the threshold value to detect area. It is to process inspection with the binary coded threshold value. After converting each pixel of the image under the threshold value to 0 and each pixel of the image over the threshold value to 1, 0 passes the area inspection, while 1 fails to pass the area inspection.				
		It sets met	hod of detecting area.			
	Extraction mode	Item	Dark object on the bright background	Bright object on the dark background		
3		Descrip tion	Extracting darker area compared to the brightness standard	Extracting brighter area compared to the brightness standard		
5		Image				


No.	Item	Description	
4	Automatic teaching	Even if user set the pass range, it teaches pass range based on the pixel of ROI.	
5	ROI type	It sets type of ROI to inspect.	
6	OK/Cancel	It registers work to work group or cancel to register.	

 $\ensuremath{\mathbb{X}}\xspace$  Threshold is the boundary value when a value is discontinuously changed.



Examples of pass/fail in the area inspection


Registering template of the inspection target (area: 13229 / pass range: 11244 to 15213)



Passed area inspection




Failed area inspection



#### 6.7.5 **Edge**

You can use the edge function to inspect the presence of the edge.

Edge compares directions of the registered edge and edges in the same area of the input image to detect the presence of the edge. It sets the pass range based on the direction of the registered edge. The edge of the inspection target in the pass range is regarded as Pass, while the edge of the inspection target out of the pass range is regarded as Fail.



No.	ltem	Description
1	Edge angle(°)	It is the measured angle value of edge grade.
2	Edge threshold	It sets threshold to detect edge. Only edges with high contrast can be detected in high edge threshold, while edges with low contrast also can be detected in low edge threshold.
3	Pass range(±°)	It sets the pass/fail range of edge. Setting range: ±0 to ±10°
4	Position threshold	It is range of the distance between edge at ROI teaching and edge detected from inspection target. If the distance between edge at ROI teaching (0) and edge detected from inspection target is within the range of position threshold, it is processed as pass.

No.	Item	Description				
			od for inspecting edge. edge along the direction of arrow in the ROI.			
		Item	Description	Image		
5	5 Edge Inspection Direction	Regardless of the direction	Detects firstly encountering edge in the ROI range.			
		Bright area → Dark area	Detects edge on the boundary line from bright area to dark area.			
		Dark area → Bright area	Detects edge on the boundary line from dark area to bright area.			
6	Automatic teaching	When user changes parameter or adjust ROI, it teaches automatically.				
7	ROI type	It sets type of ROI to inspect. ARROW (arrow) X, Y axes coordinate of the edge (A) and distance from the edge (D) are displayed. DISPOSABLE FALCON X:322, Y:200, A:42, D:0		n the edge (D) are		
8	OK/Cancel	It registers work to w	ork group or cancel to register.			

%Threshold is the boundary value when a value is discontinuously changed.

# Ex.

Examples of pass/fail in the edge inspection

Registering template of the inspection target (edge angle: 42° / pass range: ±10°)



Passed edge (alignment applied)



Failed edge



## 6.7.6 Shape comparison

You can use the shape comparison function to inspect the shape of the object.

Shape comparison compares features and patterns of the terget object in the ROI of the input image and that of the registered image.

It sets pass range based on the similarity of the ROI in the registered image and the ROI in the input image.

Similarity of the two images over the threshold is regarded as Pass, while similarity of the two images under the threshold is regarded as Fail.

	(28 66 66 년 18 1 19 1 19 1 19 1 19 1 19 1 19 1 19	4 H [0]	🛏 1fps 🕞 😰
Retwork Camera Juput Coutout Work Group Inspection			4-
Device Status	M Shape comparison Parameter           Similarity         100           Similarity Threshold         80           Edge Threshold         40		Automatic Teaching     ROI Type     RECTANGLE
VG-M04W-16E 210.124.103.8			LI NECTANOLE

No.	Item	Description
1	Similarity	It is similarity of the registered template and the detected template.
2	Similarity threshold <sup>≋1</sup>	It is similarity discrimination value for determining pass/fail.
3	Edge threshold	It sets threshold to detect edge. Only edges with high contrast can be detected in high edge threshold, while edges with low contrast also can be detected in low edge threshold.
4	Automatic teaching	Even if user set the pass range, it teaches pass range based on the pixel of ROI.
5	ROI type	It sets type of ROI to inspect.    RECTANGLE   POLYGON   CIRCLE   (rectangle/polygon/circle)
6	OK/Cancel	It registers work to work group or cancel to register.

%Threshold is the boundary value when a value is discontinuously changed.

%1. When set template of ROI is 50% similar with the input image in 50 similarity threshold, the vision sensor regards them as the same target and outputs output signal.



## Ex.

Examples of pass/fail in the shape comparison inspection

Registering template of the inspection target (Similarity: 100% / Similarity threshold: 80%)



Passed shape comparison inspection (alignment applied)

Pass



Failed shape comparison inspection

FAIL



#### 6.7.7 Length

You can use the length function to inspect the length between two edges. The length unit is pixel.

Base points of measuring length are two edges on each of two arrows. Length sets the pass range based on the length between two registered edges. The measured length of the inspection target within the pass range is regarded as Pass, while the measured length of the inspection target out of the pass range is regarded as Fail.

Vision Master - NewWork.avs* file(F) Device(D) Help(H)	[전 프 프 ] 전 ] 전 관 전 ] 스 프   Q, Q (프) x1.30 · 프   []] 등	(m) 🔲	H > H 1fps -
Inter Joekkelly helpkilj Retwork Camera Jout Output Work Group Interestion			M   K   100 *   <b>[0</b>
Device Status Device VG-M04W-16E 210.124.103.8 Deconnect	Carpoth Parameter     Pass Range 394     Edge Threshold A 50     Edge Threshold B 50	7 403	414 @ Automatic Teachin ROI Type
Work Group Status UNSAVED ] NewWork.avs <changed></changed>	988-127		V OK

No.	Item	Description
		It sets the pass/fail range of length.
1	Pass range	391 403 411
	· ····g·	Lower limit Measured ROI Upper limit
		for pass length value for pass
		It sets threshold to detect edge.
2	Edge threshold A/B	Only edges with high contrast can be detected in high edge threshold, while edges with low contrast also can be detected in low edge threshold.
3	Automatic teaching	Even if user set the pass range, it teaches pass range based on the pixel of ROI.
		It sets type of ROI to inspect.
4	ROI type	In the ROI area, the program scans the edge in the arrow direction and firstly detected edge becomes standard for inspection.
		T DOUBLE_ARROW (two arrows)
5	OK/Cancel	It registers work to work group or cancel to register.

%Threshold is the boundary value when a value is discontinuously changed.

## **Autonics**




Examples of pass/fail in the length inspection


Registering template of the inspection target (Length: 386 / pass range: 376 to 396)



Passed length inspection (alignment applied)



Failed length inspection




### 6.7.8 **Angle**

You can use the angle function to inspect the angle between two edges. The unit of angle is  $^{\circ}$  (degree).

Angle measures angle of crossing point which is between two edges of registered arrows.

It sets the pass range based on the angle between two registered edges. The measured angle of the inspection target within the pass range is regarded as Pass, while the measured angle of the inspection target out of the pass range is regarded as Fail.



No.	Item	Description	
4		It sets the pass/fail range of angle.	
		Lower limitMeasured ROIUpper limitfor passangle valuefor pass	
2	Edge threshold A/B	It sets threshold to detect edge. Only edges with high contrast can be detected in high edge threshold, while edges with low contrast also can be detected in low edge threshold.	
3	Automatic teaching	Even if user set the pass range, it teaches pass range based on the pixel of ROI.	
4	ROI type	It sets type of ROI to inspect. In the ROI area, the program scans the edge in the arrow direction and firstly detected edge becomes standard for inspection.	
5	OK/Cancel	It registers work to work group or cancel to register.	

XThreshold is the boundary value when a value is discontinuously changed.



Examples of pass/fail in the angle inspection


Registering template of the inspection target (angle: 98° / pass range: 88 to 108°)



Passed angle inspection




Failed angle inspection



#### 6.7.9 Diameter

You can use the diameter function to inspect diameter of the circle. The unit of diameter is pixel.

Diameter detects circle in the registered area which is between two circles (minimum and maximum diameter of the circle). The detected diameter within the minimum/maximum area is regarded as Pass, while the detected diameter out of the minimum/maximum area is regarded as Fail.



No.	Item	Descriptio	n		
		It sets method to detect circle. When you setting ROI, two circles are made and area between two circles is the range to detect circle.			
		Item	Outside→Inside	Inside→Outside	
5	Inspection direction	Descripti on	Scanning the pass area from outside to inside. Detecting outermost circle in multiple circles.	Scanning the pass area from inside to outside. Detecting innermost circle in multiple circles.	
		Image	Detected circle	Detected circle	
6	Automatic teaching	When user changes parameter or adjust ROI, it teaches automatically.			
7	ROI type	It sets type of ROI to inspect. CONCENTRIC_CIRCLE (concentric circle)			
8	OK/Cancel	It registers v	work to work group or cancel to	o register.	

%Threshold is the boundary value when a value is discontinuously changed.

%1. When roundness threshold is set to 50, an object with 50% of circle shape is regarded as circle.



# Ex.

Examples of pass/fail in the diameter inspection


Registering template of the inspection target (diameter: 92, / pass range: 75 to 111)



Passed diameter inspection



Failed diameter inspection



## 6.7.10 Object counting

You can use the object counting function to count the number of object.

Object counting counts the number of object in the registered ROI. It regards object with the certain amount of pixel as an object, and compares the number of detected object. The number of detected object within the pass range is regarded as Pass, while the number of detected object out of the pass range is regarded as Fail.

Ovision Master - NewWork.avs*			
File(F) Device(D) Help(H)	(26 ≜ ) (3 ) (3 2 (3 1 ≤ ) (4 , 0 ⊂ ) (1.13) · (1 ) (11 = 1) (11	9) <b>D</b> 1	I≪ ► ►I 1fps -
File(F) Device(D) Help(H)			4      4       1
C Device Status  Device VG-MO4W-16E 20.124.03.8  Disconnect  VOK-Group Status UUSAVED UUSAVED UUSAVED VUSAves  (X: 0, Y: 61)  Brightse	Object Counting Parameter Pass Range 4 Brary Threshold 127 Area FRer Threshold 100 Extraction Mode Dark on Bright		4 Q Automatic Teaching ROI Type RECTANGLE • VOK Cancel

No.	Item	Description		
		It sets the pass/fail range of object counting.		
1	Pass range	4	4	4
1	Pass range	Lower limit for pass	The measured number of ROI object	Upper limit for pass
2	Binary threshold	It sets the threshold value to detect area. Binary threshold means processing inspection with the binary coded threshold value. After converting each pixel of the image under the threshold value to 0 and each pixel of the image over the threshold value to 1, 0 passes the area inspection, while 1 fails to pass the area inspection.		
3	Area filter threshold		ue for regarding as an area. ards a group of objects with the nເ d as an area.	umber of pixels

No.	Item	Description		
		It sets method of detecting area.		
		Item Dark object on the bright background Bright object on the dark background		
4	Extraction mode	Descrip tionExtracting darker area compared to the brightness standardExtracting brighter area compared to the brightness standard		
	Extraction mode	Image		
5	Automatic teaching	When user changes parameter or adjust ROI, it teaches automatically.		
6	ROI type	It sets type of ROI to inspect.   RECTANGLE  POLYGON  CIRCLE  (rectangle/polygon/circle)		
7	OK/Cancel	It registers work to work group or cancel to register.		

\*Threshold is the boundary value when a value is discontinuously changed.




Examples of pass/fail in the object counting inspection


Registering template of the inspection target (the number of object: 4 / pass range: 4)



Passed object counting (alignment applied)



Failed object counting




## 6.7.11 Color identification

You can use the color identification function to inspect object by its color.

Color indentification compares ROI average color of registered by user and that of the input image.

Based on the average color value of registered ROI, extracted color from the input image within the color value deviation is regarded as Pass, while extracted color from the input image out of the color value deviation is regarded as Fail.



No.	Item	Description			
1	Color deviation	It is color deviation value in ROI.			
2	Color deviation mode <sup>×1</sup>	It sets mode to measure color deviation. Color deviation mode is calculating method of pass range for the input image based on the registered ROI average color value. Depending on the color deviation mode, specific setting is different.			
		Euclidean distance deviation			Manhattan distance deviation
3	Color deviation mode - specific setting	Color deviation threshold:			Red/Green/Blue: It sets pass range by applying deviation value to each of red, green, blue color.
4	ROI average color	It displays average color of ROI in a color system (color area) mode.          RGB       (RGB/CIELab         HSV       (RGB/CIELab         Item       Description         RGB       R (Red) / G (Green) / B         L: contrast (+white ↔ -         CIELab       a: Saturation (+red ↔ -		a) mode. (RGB/CIEIa G (Green) / B (+white ↔ ↔ on (+red ↔ ↔	ab/HSV) (Blue) -black) -green)
			a: Saturation (+red ↔ -green) b: Saturation (+yellow ↔ -blue)		

No.	ltem	Description	on	
		HSV	H (Hue) / S (Saturation) / V (Value, contrast)	
		CIELab and HSV are processed in RGB data.		
5	Automatic teaching	It teaches color automatically, based on the ROI registered by user. Based on color deviation which is set to "0" automatically, vision master inspects color of the input image.		
	It sets type of ROI to inspect.		of ROI to inspect.	
6	ROI type	RECTAI	NGLE	
0		DOLYG	ON	
			(rectangle/polygon/circle)	
7	OK/Cancel	It registers	work to work group or cancel to register.	


%Threshold is the boundary value when a value is discontinuously changed.

- **Euclidean distance deviation** Manhattan distance deviation Green Green Blue Blue Red Red A: Average color value of ROI A: Average color value of ROI r: Pass range for red a: Color deviation threshold g: Pass range for green Color within the deviation range which is from b: Pass range for blue "A" to "a" is regarded as Pass. Color within the deviation range from "A" to setting value of each color is regarded as Pass.
- %1: Color Deviation Mode




Examples of pass/fail in the color identification inspection

Registering template of the inspection target



Passed color identification



Failed color identification



### 6.7.12 Area of color

You can use the area of color function to inspect area of a certain color. Area means the number of pixels in a certain color.

Area of color measures area of a certain color (the number of pixel) in the ROI area of the input image.

Detected area of the color (the number of pixel) from the input image within the pass range is regarded as Pass, while detected area of the color (the number of pixel) from the input image out of the pass range is regarded as Fail.


Vision Master - Area of color.avs		
File(F) Device(D) Help(H)	(22 🚔 🖆 🖄 🖄 🖄 🖾 🖳 🔍 🔍 🔁 x1.30 🔹 🖂 🔲 🔣	(2) 🗊 🛛 🖌 🕨 Ifps 🕞
Retevork Comens Comens Duput Output Output Work Group Inspection	Wedding	4.
Device Status	Area of Color Parameter	
Device VG-C04W-8E	Pass Range 1655 1948 Color Deviation Mode Euclidean Distance Deviation	2240     QAutomatic Teaching     ROI Average Color
210.124.103.7	Color Deviation Mode Exclusion Declaration	ROI Type
Ø Disconnect		RGB RECTANGLE
a Work Group Status		G = 28
[ DEVICE ] [INDEX 8] Area of color avs		8 = 57
	97. B1153	V OK
	97. Bi 153	8 = 57

No.	Item	Description			
1	Pass range	the ROI area ( W	orking ).	ting the teaching col	2358
		Lower limit for pass	Measure area of col		Upper limit for pass
2	Color deviation mode <sup>×1</sup>	image based on th	de is calculating e registered ROI	tion. method of pass rang average color value ode, specific setting	
		Euclidean distance deviation		Manhattan distance deviation	
3	Color deviation mode - specific setting	Color deviation threshold: It sets pass range based on the ROI average color.		Red/Green/Blue: It sets pass range by applying deviation value to each of red, green, blue color.	
4	ROI average color	It displays average color of ROI in a data value, depends on the set color system (color area) mode.          RGB         CIELab         HSV         (RGB/CIElab/HSV)			ls on the set
		Item Descri	ption		

No.	Item	Description	on
		RGB	R (Red) / G (Green) / B (Blue)
			L: contrast (+white ↔ -black)
		CIELab	a: Saturation (+red ↔ -green)
			b: Saturation (+yellow ↔ -blue)
		HSV	H (Hue) / S (Saturation) / V (Value, contrast)
		CIELab and HSV are processed in RGB data.	
5	Automatic teaching	It teaches color automatically, based on the ROI registered by user. Based on color deviation which is set to "0" automatically, vision master inspects color of the input image.	
6	ROI type	It sets type	ON
7	OK/Cancel	It registers	work to work group or cancel to register.

XThreshold is the boundary value when a value is discontinuously changed.

### %1: Color Deviation Mode







Examples of pass/fail in the area of color inspection

 Registering template of the inspection target (area of color: 1948 / pass range: 1655 to 2240)




Passed area of color





Failed area of color



### 6.7.13 Object of color counting

You can use the object of color counting function to count the number of object in a certain color. Area means the number of pixels in a certain color.

User designates color to inspect from the target, and registers area to be inspected. Object of color counting inspects the number of object in a certain color in the registered ROI. It regards object with the certain amount of pixel as an object, and compares the number of detected object. The number of detected object within the pass range is regarded as Pass, while the number of detected object out of the pass range is regarded as Fail.


State - NewWork.avs*			
File(F) Device(D) Help(H)	2 2 2 2 4 4 4 4 4 2 2 4 4 4 4 2 2 4 5 4 5	(B) 🔲 H	▶ ▶I 1fps - D
Retwork Camera Camera Dout Output Work Group Inspection	<image/> <image/>		4-
Device Status	Solution Color Counting Parameter		
Device VG-C04W-8E	Pass Range 10 10	1	0 🚱 Automatic Teaching
210.124.103.7	Area Filter Threshold 200 Color Deviation Mode Euclidean Distance Deviation	<ul> <li>ROI Average Col</li> </ul>	ROI Type
	Color Deviation Threshold 30	RGB	or RECTANGLE -
Disconnect		R = 86	_
Mork Group Status		G = 25	
[ UNSAVED ] NewWork.avs <changed> ( X: 35, Y: 1 ) R: 108, 8: 11</changed>	57. Br 68	B - 11	V OK Cancel

No.	ltem	Description			
1	Pass range	It sets the pass/fail rang the ROI area ( <b>Workd</b> 10 Z Lower limit for pass	<b>ng</b> ).	。 ed number of	or ( <b>Color</b> ) in Upper limit for pass
2	Color deviation mode <sup>*1</sup>	It sets mode to measure Color deviation mode is image based on the reg Depending on the color	s calculating gistered ROI	method of pass range average color value.	
3	Color deviation mode - specific setting	Euclidean distance dev Color deviation thresho It sets pass range base ROI average color.	ld:	Manhattan distance Red/Green/Blue: It sets pass range b deviation value to e green, blue color.	by applying
4	ROI average color	It displays average colo color system (color area RGB CIELab HSV			on the set

No.	Item	Description	on	
		Item	Description	
		RGB	R (Red) / G (Green) / B (Blue)	
			L: contrast (+white ↔ -black)	
		CIELab	a: Saturation (+red ↔ -green)	
			b: Saturation (+yellow ↔ -blue)	
		HSV	H (Hue) / S (Saturation) / V (Value, contrast)	
		CIELab an	d HSV are processed in RGB data.	
5	Automatic teaching	It teaches color automatically, based on the ROI registered by user. Based on color deviation which is set to "0" automatically, vision master inspects color of the input image.		
6	ROI type	It sets type	ON	
7	OK/Cancel	It registers	work to work group or cancel to register.	

%Threshold is the boundary value when a value is discontinuously changed.

#### %1: Color Deviation Mode





Examples of pass/fail in the object of color counting inspection

 Registering template of the inspection target (the number of object: 10 / pass range: 10



Passed object of color counting



Failed object of color counting



# 7 Settings

		se select simulator or device t		G
Device	3	IP Address	MAC Address	Connectable staus
·	Simulators			
	🚜 VG-M04			
	🚜 VG-C04			
- #	Devices			
	VG-C04W-8E	210.124.103.246	58:E8:08:00:19:C6	۰
	VG-C04W-8E	210.124.103.194	58:E8:08:00:37:36	۰
	🐮 VG-M04W-16E	210.124.103.8	58:E8:08:00:26:D1	۰
	VG-C04W-8E	210.124.103.7	58:E8:08:00:25:ED	٥

No.	Items	Description
		Without vision sensor, you can register work group using an image saved in the PC for inspection test.
1	Simulator	Image: Simulator       Image: Simulator         VG-M04       Image: Work Group         Image: Connect       Image: Simulator         Image: Connect       Image: Simulator         Image: Simulator       Imag
2	Device (Vision sensor)	A list of connected vision sensors is displayed. You can select the vision sensor to use from the list of connected vision sensor. After registering work group and setting parameters, you can start inspection.


## 7.1 Simulator

1st After installing Vision Master, select the simulator, 'VG-04', in the Select device window. Or, you can check work group and inspection with the simulator.

	Please	select simulator or device to	connect.	<b>(</b> )
	Device	IP Address	MAC Address	Connectable staus
Þ	🔐 Simulators			
	器 VG-M04			
	VG-M04:Beverage			
	🐮 VG-M04:Bolt			
	VG-M04:Cap			
	器 VG-C04			
	😤 Devices			
	🐮 VG-C04W-8E	210.124.103.246	58:E8:08:00:19:C6	٥
	🐮 VG-C04W-8E	210.124.103.194	58:E8:08:00:37:36	٥
	VG-M04W-16E	210.124.103.8	58:E8:08:00:26:D1	٥
	VG-C04W-8E	210.124.103.7	58:E8:08:00:25:ED	٥
	Manual IP Address Searching	✓ Connect after changing IP	✓ OK	X Cancel

2nd Click 'Open image(O)' or 'Open all images from folder(F)' from the File(F) in the menu to load an image to inspect. You can see the loaded image in the image window and preview window in the right side of the screen.

File	(F) Help(H)	
12	Open Image(O)	
<b>B</b>	Open All Images from Folder(F)	
₽	Save Image(S)	
6	Work Group Manager(M)	
۵	New Work Group(N)	
1	Load Work Group from PC(W)	
<b>a</b>	Save Work Group to PC(K)	
×	Exit(X)	
	Vision Master - NewWorkaws File(F) Help(H)	
	Work Group	



## **Autonics**


3rd When adding work in the 'work group' setting, click [OK] button in the following pop-up message to register master image. For more details, refer to '6.6.5 Work Group'.



4th Set inspection items. For more details, refer to '6.7 Inspection'.








5th Click 'Play' icon ( $\blacktriangleright$ ) on the top right side.

You can see inspection status in the 'Inspection' setting window by playing the images of the preview window.



- 6th You can save work group registered with the simulator in the PC.
  - File(F)
     Help(H)

     Image Open Image(O)

     Open All Images from Folder(F)

     Save Image(S)

     Work Group Manager(M)


     New Work Group (N)

     Load Work Group from PC(W)


     Save Work Group to PC(K)
  - × Exit(X)

## 7.2 **Device (Vision Sensor)**

- 1st After installing Vision Master, select a device vision sensor) to use from a list of connected devices (vision sensor) by checking IP address.
- 2nd Click focusing guide in the 'Camera' setting to set the area to focus on, and adjust focus with focus adjuster. When adjusting focus with focusing guide, run Continuous snap (



3rd If taken images are dark, set the exposure time longer or light level and gain higher.



4th Select the type of input signal which performs as a camera shutter to take image by setting the trigger mode.

_ <b>Ö</b>	Trigger Mode	
	Free-Run Trigger	-
	Free-Run Trigger	
	Internal Trigger	
	External Trigger	
Camera		


#### 5th Set input and output.

Input		Bave Changes
Input	Input Mode	Active Level
Trigger	Camera Trigger	▼ U Low
Input 0	Work Group Change Bit 0	▼ JL High
Input 1	Work Group Change Bit 1	▼ JL High
Input 2	Work Group Change Bit 2	▼ JTL High
Input 3	Work Group Change Bit 3	▼ JL High
		1
	Trigger Input 0 Input 1 Input 2	Input         Input Mode           Trigger         Camera Trigger           Stype O         Work Group Change Bt 0           Input 1         Work Group Change Bt 1           Input 2         Work Group Change Bt 2

Input

Output Output Mode										
		Control	Output		Pulse Typ	9	Duration(ms)	Delay Type		Delay Time(ms)
Output 0 Disable	* NP	IPN 💌	JL N.O.	۳	Latch		10	After Inspectio		0
Output 1 Insepction Result	- NP	ipn 🔫	JL N.O.	•	Pulse	•	10	After Trigger L		500
Output 2 Inspection Complete	* NP	IPN 🔹	JL N.O.	۳	Pulse	-	10	After Inspectio	. *	0
Output 3 Alarm • FTP File	le Transmission Error • NP		JL N.O.	-	Latch	•				

6th Add work in the work group' setting. For more details, refer to '6.6.5 Work Group'.




In

7th Before starting inspection, set the result image which is displayed in the image window, and activate Save result image. For more details, refer to '(1) Device' in '6.6.6 Inspection'.

All Images	★	
Disable Passed Image Failed Image All Images		
Save Result Image		
Save Result Image		
Image Format	ВМР	
Saved Path	C:₩Users₩Administrator₩Documents₩Autonics₩Vision Master₩Image*	<b>5</b>
Storage Space Setting	100	МВу
Storage Space Usage	The number of files : 0 0	MBy
Drive Free Space	74755	MBy
	OK	XCa

- 8th Click 'Add taken image to preview window' icon (IO) on the top right side. You can see the images which is being taken by the vision sensor.
- 9th When you click Start device inspection, Select operation mode window appears. Select between Save and run and Unsave and run for registered work group.

		v	<b>v</b> 1	- 0 - X-
	Vision Master - TEST.avs File(F) Device(D) Help(H)		(0) 🖬	ньн 1fps - 🜘
				-/100
	Network		PASS	
	<u>6</u>		(A)	
	Camera		as	
	<b>→</b> ]	1994 - 1995 - 1996 - 1996 - 1996 - 1996 - 1996 - 1996 - 1996 - 1996 - 1996 - 1996 - 1996 - 1996 - 1996 - 1996 -		
Inspection	Input			
mopoolion	[→ Output	dia dia		
	Ē			
	Work Group	Ĩ		
	${\boldsymbol{ \oslash}}$			
	Inspection			
		Autonics	<b>8</b> 1	
		Sensors & Controllers		
	Device Status	evice 🧭 Inspection Status		Reset Statistics
	Device 🧭	Start Davise Inspection	Result Pass/Fal Operating Time(m 0/0(0.0%)	Input Trigger 0.0%     Pass 0
		2 Object Counting 1 9 Kesuit image	0/0(0.0%) 0/0(0.0%)	- Fal 0
	O Disconnect	uges • • • • • Brightness 1 33	0/0(0.0%)	- Work 0.0% - All Pass 0
	Work Group Status [ DEVICE ] [INDEX 5]	isable O Inspe: on Complete O Inspe: too Result O		One or More Falure 0 The Number of Works 4
	TEST.avs 2	Alarm		Overall Inspection Time(ms) -
	( ): 5, Y: 5 ) Brightness:113		0/0(0.0%)	·
	(X: 5, Y: 5) EXEMPLE	-		
	r			
	Select Operation	Mode	x	
	Wh.	en the device is turned off, unsaved data will be h	aat	
		you want to save current Work Group to the devic	e?	
		<b>L</b>		
	Save and R	un Unsave and Run Cancel		
	C .			



You can also save work group in the File menu to start inspection.

# 8 Troubleshooting

Please check routinely whether VG is operating in normal status or not.

No	Symptom	Solution				
		Check that status of power supplying and power cable connections is in normal.				
1	When supplying power, POWER LED	Check that power is being supplied within the rated range.				
1	of VG is not turned on.	Check that polarity of power is connected correctly.				
		Check that power terminal is tightened thoroughly.				
2	VG does not work due to the external	Check that whether status of input COMMON or each of input wire connection is in normal.				
2	input error.	Check that the device connected to input has a problem.				
		Check that output wire is connected correctly.				
	VG does not work due to the external	Check that power to output is being supplied within the rated range.				
3	output error.	Check that the device connected to output has a problem.				
		Check that specifications of load connected to output is within the rated range.				
		Check that LINK LED is turned on. If not, check wiring.				
4	Error occurs in Ethernet communication.	Check that communication (IP address, subnet mask, and gateway) is set correctly. Refer to '6.3.5 Network setting' to set correctly.				
		Check that connection or specification of the communication cable is corresponding to that Autonics guide. Use the Autonics cable (sold separately).				



\* Dimensions or specifications on this manual are subject to change and some models may be discontinued without notice.